

REPORT of SURVEY for REPAIRS.

Rec 4/5/65

No. in Reg. Book. **No.** 2335 Survey held at Glasgow Date 17th April 18 65
on the Snow Annie Master Thomas Jackson
Tonnage 280 Built at Sunderland When built 1858
By whom built _____ Owners W. Pippet
Port belonging to South Shields Destined Voyage Buenos Ayres
If Surveyed Afloat or in Dry Dock Patent Ship Newfrew

Last Survey, No. 9052 Port Newcastle Classed S.A. 1. ⁶³

REPAIRS Yellow Metal Sheathing, Stipped, Bottom Polished Bright, Two After Lengths of Keel together with Carboard Strakes on Port Side, runned and renewed of American Rock Elm; Keel through fastened with Iron Bolts Recaulked and Sheathed with Yellow Metal on Sill to the Wale

Present Condition of the

Decks <u>Where Seen Good</u>	Treenails <u>Where Seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>do</u>	Breasthooks and Stenson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>do</u>	Timbers of the Frame at the openings <u>do</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Ditto Ditto at other places <u>do</u>	Sails <u>do</u>
Planksheers <u>do</u>	Keelsons <u>do</u>	Anchors No. of <u>3 Bk 1 Stem 2 Midge</u>
Sheerstrakes <u>do</u>	Clamps and Shelves <u>do</u>	Cables <u>Complete</u>
Topsides <u>do</u>	Ceiling <u>do</u>	Hawsers and Warps <u>do</u>
Wales <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter <u>do</u>	Copper <u>Yellow Metal</u> When put on <u>1865</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. new & good & tested
Is in good Condition Eligible to remain as Classed

The Amount of Fee.....£ 10 : 0 : 0 is received by me,

Special..... / : 0 : 0

Certificate (if required) : do

Committee's Minute 5th May 18 65

Character assigned S.A. 1 record repair

Handwritten signature