

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No. 2337** Survey held at Glasgow Date 19th April 1865
 on the Snow "Susitania" Master H. Edwards
 Tonnage 207 Built at Glasgow When built 1860
 By whom built Watt Owners John Mitchell
 Port belonging to Glasgow Destined Voyage Lisbon
 If Surveyed Afloat or in Dry Dock Patent Ship Alexander Stephen & Sons

Last Survey, No. 1935 Port Glasgow Classed G.A. 1
 REPAIRS Yellow Metal Sheathing Shipped, Bottom Brightened, Recaulked and Sheathed with Yellow Metal on Selt to the upper part of hulls Windlass Shipped, Examined and found good

Present Condition of the

Decks <u>Where Seen Good</u>	Treenails <u>Where Seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>do</u>	Timbers of the Frame at the openings <u>do</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Ditto Ditto at other places <u>do</u>	Sails <u>do</u>
Planksheers <u>do</u>	Keelsons <u>do</u>	Anchors No. of <u>3 1/2 Iron Wedge</u>
Sheerstrakes <u>do</u>	Clamps and Shelves <u>do</u>	Cables <u>Complete</u>
Topsides <u>do</u>	Ceiling <u>do</u>	Hawsers and Warps <u>do</u>
Wales <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter <u>do</u>	Copper <u>Yellow Metal</u> When put on <u>1865</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Now & Good & how tested
As in good Condition Eligible to remain as Chafed


The Amount of Fee.....£ : : is received by me,

Special..... / : / :

Certificate (if required) " : " :

Committee's Minute 5th May 1865

Character assigned G.A. 1



© 2019

Lloyd's Register Foundation

GLS143-0376