

## REPORT of SURVEY for REPAIRS.

Rec 31/5/66

No. in Reg. Book. **No. 2483** Survey held at **Glasgow** Date **16th May** 18**66**  
 on the **S.S. "Lusitania"** Master **David James**  
 Tonnage **207** Built at **Glasgow** When built **1860**  
 By whom built **Watt** Owners **John Mitchell**  
 Port belonging to **Glasgow** Destined Voyage **Lisbon**  
 If Surveyed Afloat or in Dry Dock **Alexander Stephen & Sons Patent Slip**

Last Survey, No. **2337** Port **Glasgow** Classed **G.A. 1.**  
 REPAIRS **Yellow Metal Sheathing Shipped, Bottom Rubbed Bright, recalked and Sheathed with Yellow Metal on Sill to upper part of Wale**

## Present Condition of the

Decks <b>Good where seen</b>	Treenails <b>Good where seen</b>	Windlass and Capstan <b>Good</b>
Waterways <b>do</b>	Breasthooks and Stemson <b>do</b>	Pumps <b>do</b>
Comings <b>do</b>	Transoms, Pointers, and Crutches <b>do</b>	Boats <b>do</b>
Upper Deck Beams & Fastenings <b>do</b>	Timbers of the Frame at the openings <b>do</b>	Masts, Yards, &c. <b>do</b>
Lower Deck Beams & Fastenings <b>do</b>	Ditto Ditto at other places <b>do</b>	Condition, how ascertained <b>from Examination</b>
Planksheers <b>do</b>	Keelsons <b>do</b>	Sails <b>Complete</b>
Sheerstrakes <b>do</b>	Clamps and Shelves <b>do</b>	Anchors No. of <b>3 B. 1 Stem 2 Wedge</b>
Topsides <b>do</b>	Ceiling <b>do</b>	Cables <b>Complete</b>
Wales <b>do</b>	Rudder <b>do</b>	Hawsers and Warps <b>do</b>
Plank (Bottom) and Counter <b>do</b>	Copper <b>Yellow Metal</b> When put on <b>1866</b>	Standing & Running Rigging <b>do</b>

## General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. **do & Good where tested**

**do in good Condition where seen, Eligible in my opinion to remain as shipped**

The Amount of Fee.....£ : : is received by me.

Special..... / : / : &gt;

Certificate (if required) : : : &gt;

Committee's Minute **1st Dec 1866**Character assigned **G.A. 1** record **G.M.**

© 2019

Lloyd's Register  
Foundation

GLS143-0459