

REPORT of SURVEY for REPAIRS.

Rev 5/11/66

No. in Reg. Book. **No. 2542** Survey held at Glasgow Date 3rd November 1866
 on the City of Dundee Master R. Phillips
 Tonnage 1005 Built at Dumbarton When built 1863
 By whom built Parker Owners Albia S. Co
 Port belonging to Glasgow Destined Voyage India
 If Surveyed Afloat or in Dry Dock Ed. J. Haynes Dry Dock

Last Survey, No. 19523 Port Liverpool Classed 10 65

REPAIRS

of Damage: in consequence of taking the ground in the Hayley. Shipped metal off the Gunbrad strake and keel to test the Caulking. found to be in good condition. Patched yellow metal where required

Present Condition of the

Decks <u>Good where seen</u>	Treenails <u>Good where seen</u>	Windlass and Capstan <u>Good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the openings <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto Ditto at other places <u>"</u>	Condition, how ascertained <u>from examination and testing</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Sails <u>Good</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>3 Bows 1 Stern 2 Heads</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Cables <u>Good and sufficient</u>
Wales <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Plank (Bottom) and Counter <u>"</u>	Copper <u>Yellow metal</u> When put on <u>1865</u>	Standing & Running Rigging <u>"</u>

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

Good where tested
 This vessel appears to be in good and efficient condition and fit in my opinion to remain as Classed

The Amount of Fee.....£2-2-0 is received by me,

Special.....7: 4: 5


Certificate (if required) 7: 4: 5

J. H. Little

Committee's Minute 6th November 1866

Character assigned 10/12/1

MA



© 2019

Lloyd's Register Foundation

GLS143-0492