

REPORT of SURVEY for REPAIRS.

3198

Recd 8/9/70

No. in Reg. Book. 210 No. 3198 Survey held at Glasgow Date, first Survey 19th Last Survey 22nd Aug^r 1870.
 on the Bk "Alaska" Master Gilchrist
 Tonnage 335 built at P. E. Island When built 1869, 7 Mo
 By whom built Davies Owners W. Cruickshank
 Port belonging to Glasgow Destined Voyage ✓
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 22237 Port Live. Classed 7 A. 1
 REPAIRS, &c. now done. 3. 70

Four strakes of yellow metal on
 1/4" Red pine sheathing over felt, fastened with
 3 inch copper nails.

Present Condition of the

Decks	Treenails	Windlass and Capstan	<u>Good</u>
Waterways	Breasthooks and Stemson	Pumps	<u>Do</u>
Comings	Transoms, Pointers, and Crutches	Boats	<u>Do</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.	<u>Do</u>
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained	<u>seen from deck</u>
Planksheers	Keelsons	Sails	
Sheerstrakes	Clamps and Shelves	Anchors No. of	<u>Good</u>
Topsides	Ceiling	Cables	<u>and</u>
Wales	Rudder	Hawsers and Warps	<u>Sufficient</u>
Plank (Bottom) and Counter	Copper <u>part new</u> When put on <u>Good when new</u>	Standing & Running Rigging	<u>Good</u>
Engine Room Skylights <u>Good</u>	Caulking of	Cargo and Main Hatchways <u>Good</u>	Hatches <u>Good</u>
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways <u>Good when new</u>	Scuppers <u>Good</u>	

General Observations and Opinion;

This Vessel is now in good, and efficient
 condition, and in my opinion eligible to remain as classed.

The Amount of Entry Fee.....£ / : : : is received by me,

Special..... " : " : "

Certificate (if required) " : " : "

Committee's Minute 9th September 1870

Character assigned 7 A. 1

Tom Moverly

