

ANNUAL SURVEYS.

3378

Rec 6/9/71

No. 3378 Survey held at Glasgow Date 28th Aug 1871
 on the 13th Mye Master Stedford
 Tonnage 348 Built at Sunderland When built 1863
 By whom built Blumer Owners Dunlop
 Port belonging to Glasgow Destined Voyage Buenos Ayres
 If Surveyed Afloat or in Dry Dock Barclays Patent Slip

Last Survey, No. 22929 Port of Liv.

Classed 9 A. 1
H. T. 69 8.71

The present Condition of the

Decks	Treenails	Windlass and Capstan	<u>Good</u>
Waterways	Breasthooks and Stemson	Pumps	<u>D^o</u>
Comings	Transoms, Pointers, and Crutches	Boats	<u>D^o</u>
Upper Deck Beams & Fastenings	Timbers of the Frame <u>at the Openings</u>	Masts, Yards, &c.	<u>D^o</u>
Lower Deck Beams & Fastenings	Do Do <u>at other places</u>	Sails	<u>D^o</u>
Planksheers	Keelsons	Anchors No. of	<u>Good, and</u>
Sheerstrakes	Clamps and Shelves	Cables	<u>Sufficient</u>
Topsides	Ceiling	Hawsers and Warps	<u>Good</u>
Wales	Rudder	Standing & Running Rigging	<u>Good</u>
Plank (Bottom) and Counter	Copper <u>Good</u> When put on <u>1869</u>		

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where tested.
This vessel is now in good and efficient condition where seen, and is eligible under the amended Table A to be raised to the 10 Years Class, which is submitted for the favourable consideration of the Committee.

Committee's Minute 12th September 1871

Character assigned Raised to 10A

T. Moverly
See G2-2-0 Certificate (if required) 5/-

No. _____ Survey held at _____ Date _____ 18____
 on the _____ Master The above named vessel is
 Tonnage _____ Built at _____ When built entitled to be raised to the
 By whom built _____ Owners 10A 1 Class under the
 Port belonging to _____ Destined Voyage amended Table A.
 If Surveyed Afloat or in Dry Dock _____ 12/9/71 B.M.

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame <u>at the Openings</u>	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Do Do <u>at other places</u>	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper _____ When put on _____	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways

Committee's Minute _____ 18____

Character assigned _____