

REPORT of SURVEY for REPAIRS.

3555

Completion of Survey No 3407

Re 10/10/72

No. in Reg. Book. **No. 3555** Survey held at **Glasgow** Date, first Survey **26th Sept** Last Survey **7th October** 18**72**

on the **Schooner Sapphire** Master **Darroch**

Tonnage **167** built at **Greenock** When built **1846**

By whom built _____ Owners **McArthur Bros**

Port belonging to **Glasgow** Destined Voyage **Glas. Liverpool**

If Surveyed Afloat on in Dry Dock **at West Street Quay**

Last Survey, No. **3407** Port **Gls.** Classed **11** **Atin red**

S.S. 471 7/11. 11.71

REPAIRS, &c.

As promised by the Owners - the deck renewed with Baltic pine.

Present Condition of the

Decks <i>new good</i>	Treenails <i>good</i>	Windlass and Capstan <i>good</i>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c. <i>And</i>
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables <i>Sufficient</i>
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper <input checked="" type="checkbox"/> When put on <input checked="" type="checkbox"/>	Standing & Running Rigging
Engine Room Skylights	Caulking of	
Coal Bunker Openings, Lids, &c.	Bottom, Deck, & Waterways <i>good</i>	
	Scuppers <i>good</i>	Cargo and Main Hatchways <i>good</i> Hatches <i>good</i>

General Observations and Opinion,

This vessel is in good and efficient condition fit for the safe conveyance of any and perishable cargoes to and from all ports of the world. eligible to remain as classed Atin red.

The Amount of Entry Fee.....£ *4 : 4 : -* is received by me,

Special..... *1 : 1 : -*

Certificate (if required) " : " : "

Committee's Minute *11th October 1872*

Character assigned *Atin red*

W. Thompson

second New Deck
TBW



© 2019
Lloyd's Register
Foundation
GLS144-0434