

REPORT of SURVEY for REPAIRS.

3609

No. in Reg. Book. 170 Survey held at Glasgow Date, first Survey 10th Dec^r Last Survey 10th Dec^r 1872
 on the Coast Ship Wild Deer Master - Whitson
 Tonnage 1126 built at Glasgow When built 1863
 By whom built Chas. Smith Owners Albion Shipping Co^y
 Port belonging to Glasgow Destined Voyage Clas. New Zealand
 If Surveyed Afloat or in Dry Dock in the Harbour
 Last Survey, No. 3444 Port Gls. Classed 16A
 REPAIRS, &c. SS Cl. 70 1/2

of Damage

On the port side, one length of plank sheer and four rough tree stentings renewed with teak three prop beams, cracked at their turned ends, repaired with liner plates. Ribs and bulwarks partly renewed -

Present Condition of the

Decks	<u>Good</u>	Treenails <u>Blind rivets</u>	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways		Breasthooks and Stemson		Pumps	<u>?</u>
Comings		Transoms, Pointers, and Crutches		Boats	<u>2nd</u>
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	<u>?</u>
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	<u>Suff^y</u>
Plank sheers	<u>Where</u>	Keelsons	<u>Where</u>	Sails	<u>?</u>
Sheerstrakes		Clamps and Shelves		Anchor No. of	<u>Where</u>
Topsides		Ceiling		Cables	<u>?</u>
Wales		Rudder	<u>Seen</u>	Hawsers and Warps	<u>Seen</u>
Plank (Bottom) and Counter	<u>Seen</u>	Copper <u>When put on</u>	<u>1872</u>	Standing & Running Rigging	<u>?</u>
Engine Room Skylights		Caulking of			
Coal Bunker, Openings, Lids, &c.		Bottom, Deck, & Waterways	<u>Good & new</u>		
Scuppers	<u>Good</u>	Cargo and Main Hatchways	<u>Good</u>	Hatches	<u>Good</u>

General Observations and Opinion,

This ship is in good and efficient condition. eligible to remain as classed 16A

The Amount of Entry Fee.....£ : : : is received by me,

Special..... / : / :

Certificate (if required) : : : :

Committee's Minute 31st December 18 72

Character assigned 16A