

# REPORT of SURVEY for REPAIRS, &c.

Rev 5/10/74

No. in  
Reg. Book.

472

No. 3908 Survey held at Glasgow

Date, first Survey 15 Sept

Last Survey 21 September

1874

on the Ship "County of Seilshire"

Master

J. G. Cairns

Tonnage

999

built at

Glasgow

When built

1868-1870

By whom built

Cornell

Owners

T. & J. Craig

Port belonging to

Glasgow

Destined Voyage

If Surveyed Afloat or in Dry Dock

Henderson's Dry Dock & Boat

Last Survey, No.

3574

Port

Glasgow

Classed

14

Character in Register Book.

AN

REPAIRS, OR EXAMINATION AS PER RULE

All the yellow metal sheathing stripped off and the bottom re-sheathed with yellow metal. A portion of the caulking removed, timbers cleared and floor plates scraped and painted.

Cause of Repairs to be clearly stated.

Present Condition of the

Decks

Good

Waterways

Keelsons

Bolts

Good

Comings

Breasthooks and Stemson

Good

Upper Deck Beams & Fastenings

Transoms, Pointers, and Crutches

Good

Lower Deck Beams & Fastenings

Timbers of the Frame at the openings

Good

Planksheers

Ditto

Ditto at other places

Good

Sheerstrakes

Keelsons

Good

Topsides

Clamps and Shelves

Good

Wales

Ceiling

Good

Plank (Bottom) and Counter

Rudder

Good

Engine Room Skylights

Copper G. In When put on Now

Caulking of

Bottom, Deck, & Waterways

Good

Windlass and Capstan

Good

Pumps

Good

Boats

Good

Masts, Yards, &c.

Good

Condition, how ascertained

from deck

Sails

Good

Anchors

No. of 3 B. 1 S. 2 R.

Cables

Good

Hawsers and Warps

Good

Standing & Running Rigging

Sufficient

General Observations, Opinion as to Class, &c.

This vessel is now in good condition and in my opinion eligible to remain as classed

The Amount of Entry Fee ...

Special ...

Certificate (if required) ...

(Travelling Expenses, if any, £ ...)

Committee's Minute

Character assigned

received by me,

24th Oct 1874

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register Foundation

GLS141-0038