

ANNUAL SURVEYS.

3983

No. 3983 Survey held at Glasgow Date 16th Feby 1875
 on the Barque Mary Lee Master Robt. Pearson
 Tonnage 444 Built at Maryport When built 1859
 By whom built R. Pitson & Co. Owners Jas. McNeil & others
 Port belonging to Maryport Destined Voyage Monte Video
 If Surveyed Afloat or in Dry Dock On Stobcross Slip and Afloat

Last Survey, No. 2886 Port of Whitehaven Classed 14 A 1
 Cont. Mpt 73-9 years
 10/73

The present Condition of the

| | | |
|---|--|---|
| Decks <u>Good</u> | Treenails <u>Good</u> | Windlass and Capstan <u>Good</u> |
| Waterways <u>do</u> | Breasthooks and Stemson <u>do</u> | Pumps <u>Good & efficient</u> |
| Comings <u>do</u> | Transoms, Pointers, and Crutches <u>do</u> | Boats <u>3 no. Good</u> |
| Upper Deck Beams & Fastenings <u>do</u> | Timbers of the Frame at the Openings <u>do</u> | Masts, Yards, &c. <u>In good condition</u> |
| Lower Deck Beams & Fastenings <u>do</u> | Ditto ditto at other places <u>do</u> | Sails <u>Well Found</u> |
| Planksheers <u>do</u> | Keelsons <u>do</u> | Anchors, No. of <u>3 B. 1 S. 2 K</u> |
| Sheerstrakes <u>do</u> | Clamps and Shelves <u>do</u> | Cables <u>Complete</u> |
| Topsides <u>do</u> | Ceiling <u>do</u> | Hawsers and Warps <u>Well Found</u> |
| Wales <u>do</u> | Rudder <u>do</u> | Standing and Running Rigging <u>In good order</u> |
| Plank (Bottom) and Counter <u>Where seen Good</u> | Copper <u>Y. Metal</u> When put on <u>1873</u> | |

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways as far as seen good

Bottom sighted Yellow Metal sheathing patchull where necessary
 Is in good and efficient condition eligible to remain as classed

Committee's Minute 5th March 1875

Character assigned

Cow 9A

Saml. Laphorn

Certificate (if required).

No. 3983 Survey held at Glasgow Date 2nd March 1875
 on the Scr. Sapphire Master Hugh McDougall
 Tonnage 167 Built at Grunock When built 1846
 By whom built Wm. Scott & Son Owners McArthur Bros.
 Port belonging to Glasgow Destined Voyage Coaster
 If Surveyed Afloat or in Dry Dock On Stobcross Slip and Afloat

Last Survey, No. 3625 Port of Glasgow Classed 10 A 1 in Red
 S.S. Cl. 71-7 yrs. 2/73

The present Condition of the

| | | |
|---|--|---|
| Decks <u>Good</u> | Treenails <u>Good</u> | Windlass and Capstan <u>Good</u> |
| Waterways <u>do</u> | Breasthooks and Stemson <u>do</u> | Pumps <u>do</u> |
| Comings <u>do</u> | Transoms, Pointers, and Crutches <u>do</u> | Boats <u>do</u> |
| Upper Deck Beams & Fastenings <u>do</u> | Timbers of the Frame at the Openings <u>do</u> | Masts, Yards, &c. <u>In good condition</u> |
| Lower Deck Beams & Fastenings <u>do</u> | Ditto ditto at other places <u>do</u> | Sails <u>Well Found</u> |
| Planksheers <u>do</u> | Keelsons <u>do</u> | Anchors, No. of <u>2 B. 1 S. 1 K.</u> |
| Sheerstrakes <u>do</u> | Clamps and Shelves <u>do</u> | Cables <u>Complete</u> |
| Topsides <u>do</u> | Ceiling <u>do</u> | Hawsers and Warps <u>Well Found</u> |
| Wales <u>do</u> | Rudder <u>do</u> | Standing and Running Rigging <u>In good Order</u> |
| Plank (Bottom) and Counter <u>do</u> | Copper <u>Single</u> When put on <u>—</u> | |

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

Bottom sighted, Caulked from Kiel to Gunwale and over all
 Hatch coaming repaired — Bottom coated — Is in good and efficient
 condition eligible to remain as classed

Committee's Minute 5th March 1875

Character assigned

A in red

Saml. Laphorn
See Return for List
 Certificate (if required).
Survey for Foundation
 Mch 1875