

ANNUAL SURVEYS.

5318 Rec 10/3/51

No. 5318 Survey held at Glasgow Date 23rd February 1881
 on the S.S. "Penfawshlee" Master Taylor
 Tonnage 506 Built at Port Glasgow When built 1870-6th
 By whom built Blackwood Owners A. J. Seligmann & Co.
 Port belonging to Glasgow Destined Voyage France
 If Surveyed Afloat or in Dry Dock Aithun + Mansels Sliz + Afloat

Last Survey, No. 28838 Port of Iron Classed B Spot check
 S.S. No 2-80 1.80

The present Condition of the

Decks	<u>Good</u>	<u>Transoms</u>	<u>Ports</u>	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	"	Breasthooks and Stemson	<u>Not seen</u>	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	<u>3</u>
Upper Deck Beams & Fastenings	"	Transoms of the Frame at the Openings	"	"	Masts, Yards, &c.	<u>From deck</u>
Lower Deck Beams & Fastenings	"	Decks at other places	"	"	Sails	"
Planksheers	"	Keelsons	"	"	Anchors, No. of	<u>3 B. 1 S. 2 K</u>
Sheerstrakes	"	Clamps and Shelves	"	"	Cables	<u>Good</u>
Topsides	"	Ceiling	"	"	Hawsers and Warps	<u>And</u>
Wales	"	Rudder	"	"	Standing and Running Rigging	<u>Sufficient</u>
Plank (Bottom) and Counter	"	<u>Copper Cement</u> When put on <u>1870</u>				

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good

The Bottom cleaned and painted. It now in good condition in my opinion eligible to remain as classed.

Committee's Minute Friday, March 11th, 18 81.

Character assigned B-1

J. Lawrence
 Certificate (if required).

No. 5318 Survey held at Glasgow Date 8th March 1881
 on the Ship "City of Bombay" Master J. Lowells
 Tonnage 931 Built at Glasgow When built 1862
 By whom built Stephen Owners E. Smith & Co.
 Port belonging to Glasgow Destined Voyage San Francisco
 If Surveyed Afloat or in Dry Dock Dry Dock + Afloat

Last Survey, No. 26303 Port of Iron Classed A
 S.S. No 3-76 1.80 5.80

The present Condition of the

Decks	<u>Good</u>	<u>Transoms</u>	<u>Ports</u>	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	"	Breasthooks and Stemson	<u>Not seen</u>	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	<u>4</u>
Upper Deck Beams & Fastenings	"	Transoms of the Frame at the Openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Decks at other places	"	"	Sails	"
Planksheers	"	Keelsons	"	"	Anchors, No. of	<u>3 B. 1 S. 2 K</u>
Sheerstrakes	"	Clamps and Shelves	"	"	Cables	<u>Good</u>
Topsides	"	Ceiling	"	"	Hawsers and Warps	<u>And</u>
Wales	"	Rudder	"	"	Standing and Running Rigging	<u>Sufficient</u>
Plank (Bottom) and Counter	"	<u>Copper Cement</u> When put on <u>—</u>				

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good

The Bottom cleaned and painted. It now in good condition in my opinion eligible to remain as classed.

Committee's Minute Friday, March 11th, 18 81.

Character assigned A-1

J. Lawrence
 Certificate (if required).

