

ANNUAL SURVEYS.

30th MAY, 82.

No. 5418 Survey held at Glasgow Date, first Survey 19th May Last Survey 19th May 1882
Reg. Book. 336 on the S.S. "Berledi" Master J. Ross
Tonnage { Net 1000 Built at Glasgow When built 1871 Year. 8 Month. 8
Gross 1557 By whom built Barclay, Curle Owners W. Thomson & Co
Under Dk. 1543 Port belonging to Leith Destined Voyage Hongkong
If Surveyed Afloat or in Dry Dock Govan Dry Dock (State Name of Dock.)

Last Survey, No. 28693 Port of Leith Classed S.S. No 2. 80 Years assigned. 100 A1 Character in Register Book. 12. 80
Present Condition of the Decks Good Good Good
Waterways " Breasthooks and Stemson "
Comings " Transoms, Pointers, and Crutches "
Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
Lower Deck Beams & Fastenings " Ditto ditto at other places "
Planksheers " Keelsons "
Sheerstrakes " Clamps and Shelves "
Topsides " Ceiling "
Wales " Rudder "
Plank (Bottom) and Counter " Copper or Y.M. Paint When put on Now
Engine Room Skylights Good Caulking of Bottom, Deck, & Waterways Good
Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
General Observations, Opinion as to Class, &c. The Bottom of this vessel has been cleaned & coated
she is appearing in good condition & is in an opinion eligible to remain as
classed.

Committee's Minute

Character assigned

Friday, 2nd June, 1882.

W Davidson William Wilson
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18

No. 5418 Survey held at Glasgow Date, first Survey 22 May Last Survey 22 May 1882
Reg. Book. 209 on the S.S. "Behera" Master Robt. Patten
Tonnage { Net 1032 Built at Newcastle When built 1864 Year. 2 Month. 2
Gross 1384 By whom built Marshall Owners W. Silburn
Under Dk. 1366 Port belonging to Glasgow Destined Voyage Odessa
If Surveyed Afloat or in Dry Dock Govan Dry Dock (State Name of Dock.)

Last Survey, No. 25620 Port of Leith Classed S.S. No 3. 79 Years assigned. A1 Character in Register Book. 2. 80
Present Condition of the Decks Good Good Good
Waterways " Breasthooks and Stemson "
Comings " Transoms, Pointers, and Crutches "
Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
Lower Deck Beams & Fastenings " Ditto ditto at other places "
Planksheers " Keelsons "
Sheerstrakes " Clamps and Shelves "
Topsides " Ceiling "
Wales " Rudder "
Plank (Bottom) and Counter " Copper or Y.M. Paint When put on Now
Engine Room Skylights Good Caulking of Bottom, Deck, & Waterways Good
Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
General Observations, Opinion as to Class, &c. The Rudder of this vessel has been lifted & bushed & a
number of rivets in same renewed & the Bottom cleaned & coated, she is
appearing in good condition & is in my opinion eligible to remain as
classed.

Committee's Minute

Character assigned

Friday, 2nd June, 1882.

W Davidson
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18

GLS146-0407