

ANNUAL SURVEYS.

No. 5489 Survey held at Glasgow Date, first Survey 4 July Last Survey 4 July 1882
 No. in Reg. Book. on the Iron S. Jessie Readman Master W. Gibson
 Tonnage { Net 962 Built at Greenock When built 1869 11
 Gross 1013
 Under Dk. 898 By whom built Scott & Co. Owners Albion Shipping Co.
 Port belonging to Glasgow Destined Voyage New Zealand
 If Surveyed Afloat or in Dry Dock Ingliston slip
 (State Name of Dock.)

Last Survey, No. 5431 Port of Gls

Classed

Years assigned.

Character in Register Book.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunkers, Openings, Lids, &c.

Scuppers

General Observations, Opinion as to Class, &c.

Transoms, Rivets

Breasthooks and Stenon

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shells

Ceiling

Rudder

Copper or Y.M.

When put on

Caulking of

Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors, No. of

Cables

Hawsers and Warps

Standing and Running Riggings

Hatches

The bottom of the vessel cleaned and re-coated.
 She is now in good and efficient condition and is eligible
 in my opinion to remain as classed.

Committee's Minute

Tuesday, 1st August, 18 82.

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin)

Paid

18

No. 5489 Survey held at Glasgow Date, first Survey 27 July Last Survey 27 July 1882
 No. in Reg. Book. on the Iron S.S. Nithsdale Master R. Lawrence
 Tonnage { Net 784 Built at Port Glasgow When built 1881 1
 Gross 1232
 Under Dk. 907 By whom built Buncliff & Dunlop Owners R. Mackill & Co.
 Port belonging to Glasgow Destined Voyage Genoa
 If Surveyed Afloat or in Dry Dock Govan dry dock
 (State Name of Dock.)

Last Survey, No. 7937 Port of Gnk

Classed

Years assigned.

Character in Register Book.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunkers, Openings, Lids, &c.

Scuppers

Observations, Opinion as to Class, &c.

Transoms, Rivets

Breasthooks and Stenon

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shells

Ceiling

Rudder

Copper or Y.M.

When put on

Caulking of

Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors, No. of

Cables

Hawsers and Warps

Standing and Running Riggings

Hatches

The bottom cleaned and recoated.
 This vessel is now in good and efficient condition and is eligible
 in my opinion to remain as classed.

Committee's Minute

Tuesday, 1st August, 18 82.

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin)

Paid

18