

## ANNUAL SURVEYS.

No. 5912 Survey held at Glasgow Date, first Survey 18<sup>th</sup> Nov Last Survey 18<sup>th</sup> Nov 1882

No. in Reg. Book. 814 on the S. S. "Clan Macrae" Master R. McEvor  
 Net 1437 Built at Sunderland When built 1881 11  
 Gross 2197  
 Under Dk. 2034 By whom built Barham, Owners Gayze Irvine & Co  
 Port belonging to Glasgow Destined Voyage Cape of Good Hope  
 If Surveyed Afloat or in Dry Dock Goran Dry Dock (State Name of Dock.)

Last Survey, No. 5701 Port of Gls.  
 Present Condition of the Decks Good  
 Waterways " Breasthooks and Stemson Good  
 Comings " Transoms, Pointers, and Crutches Good  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings " Good  
 Lower Deck Beams & Fastenings " Ditto ditto at other places " Good  
 Planksheers " Keelsons " Good  
 Sheerstrakes " Clamps and Shelves " Good  
 Topsides " Ceiling " Good  
 Wales " Rudder " Good  
 Plank (Bottom) and Counter " Copper or Y.M. Paint When put on Nov Good  
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c.

Classed 100A1  
 Years assigned 5-82  
 Character in Register Book.

This vessel has been placed in Graving Dock, the bottom cleaned & scraped, she is appearing in good condition, & is in my opinion eligible to remain as classed.

Committee's Minute Tuesday, 28<sup>th</sup> November, 1882.  
 Character assigned 100A1  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

No. 5912 Survey held at Glasgow Date, first Survey 23<sup>rd</sup> Nov Last Survey 23<sup>rd</sup> Nov 1882

No. in Reg. Book. 547 on the Ship "Loch Lomond" Master O. J. Simpson  
 Net 1200 Built at Glasgow When built 1870 1  
 Gross 1249  
 Under Dk. 1128 By whom built J. G. Harrie Owners Glasgow Shipping Co  
 Port belonging to Glasgow Destined Voyage Melbourne  
 If Surveyed Afloat or in Dry Dock Goran Dry Dock (State Name of Dock.)

Last Survey, No. 5595 Port of Gls.  
 Present Condition of the Decks Good  
 Waterways " Breasthooks and Stemson Good  
 Comings " Transoms, Pointers, and Crutches Good  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings " Good  
 Lower Deck Beams & Fastenings " Ditto ditto at other places " Good  
 Planksheers " Keelsons " Good  
 Sheerstrakes " Clamps and Shelves " Good  
 Topsides " Ceiling " Good  
 Wales " Rudder " Good  
 Plank (Bottom) and Counter " Copper or Y.M. Paint When put on Nov Good  
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c.

Classed S.S. No 3. 82  
 Years assigned 1-82  
 Character in Register Book. A1

This vessel has been placed in Graving Dock, the bottom cleaned & scraped, she is appearing in good condition, & is in my opinion eligible to remain as classed.

Committee's Minute Tuesday, 28<sup>th</sup> November, 1882.  
 Character assigned TRW  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

GLS 147-0201