

## ANNUAL SURVEYS.

No. 6224 Survey held at Glasgow Date, first Survey 24 Aug. Last Survey 24 Aug. 1883  
 No. in Reg. Book. 700 on the Iron S.S. "Sherryware" Master Stirling  
 Tonnage { Net 520 Built at Belfast When built 1882 10  
 Gross 994  
 Under Dk. 709 By whom built Martinson Clark & Co. Owners Clyde Shipping Co.  
 Port belonging to Glasgow Destined Voyage Coasting  
 If Surveyed Afloat or in Dry Dock Inglist's slip.  
 (State Name of Dock)

Last Survey, No. 2916 Port of Bel

Classed 100 A. 1.  
 Years assigned 12.82.  
 Character in Register Book.

Present Condition of the

Decks good Transoms good  
 Waterways good Breasthooks and Stems good  
 Comings " Transoms, Riggers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shells "  
 Topside Plating Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. When put on "  
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good  
 General Observations, Opinion as to Class, &c.

The bottom of the vessel cleaned and recoated.  
The vessel is now in good and efficient condition and is  
eligible in my opinion to remain as classed.

Committee's Minute

FRIDAY 7 SEPT 1883 18

Character assigned

100 A. 1

J. Stanbury.

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

No. 513 Survey held at Glasgow Date, first Survey 23 Aug. Last Survey 23 Aug. 1883  
 No. in Reg. Book. 513 on the Iron Bk. Emily Chaplin Master G. E. Harris  
 Tonnage { Net 733 Built at Bunderland When built 1875 9  
 Gross 777  
 Under Dk. 698 By whom built Austin & Hunter Owners Moran & Sanderson  
 Port belonging to Hull Destined Voyage Brisbane  
 If Surveyed Afloat or in Dry Dock Henderson's dry dock  
 (State Name of Dock)

Last Survey, No. 5349 Port of Hull

Classed 100 A. 1.  
 Years assigned 10.81.  
 Character in Register Book.

Present Condition of the

Decks good Transoms good  
 Waterways good Breasthooks and Stems good  
 Comings " Transoms, Riggers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shells "  
 Topsides Plating Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. When put on "  
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers good Cargo and Main Hatchways good Hatches good  
 General Observations, Opinion as to Class, &c.

The bottom of the vessel cleaned and recoated, and the rudder  
lifted and painted.  
This vessel is now in good and efficient condition and is eligible  
in my opinion to remain as classed.

Committee's Minute

FRIDAY 7 SEPT 1883 18

Character assigned

100 A. 1

J. Stanbury.

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

GLS148-0200

(If a Steam Ship, state if a Report is also sent on the Machinery)

(If a Steam Ship, state if a Report is also sent on the Machinery)

(Form No. 3 for Annual Survey, when there are no repairs. 4000-26/4/82.)

(Insert Character precisely as in Register Book.)

(Insert Character precisely as in Register Book.)