

# ANNUAL SURVEYS.

No. 4393 Survey held at Glasgow Date, first Survey 23<sup>rd</sup> Dec 1883 Last Survey 4<sup>th</sup> Jan 1884  
 No. in Reg. Book. 462 on the Iron barque "Brodiack Bay" Master J. Lindsay  
 Net 453 Built at Dumbarton When built 1848 Month 2  
 Tonnage Gross 448 Under Dk. 426 By whom built Birrell, Stenhouse & Co. Owners Hatfield, Cameron & Co.  
 Port belonging to Glasgow Destined Voyage Otago  
 If Surveyed Afloat or in Dry Dock Govan Dry Dock (State Name of Dock.)

Last Survey, No. 41950 Port of Low Classed 100 H.L. 10, 82  
 Present Condition of the Decks Good Moulded depth 19' 4"  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, ~~Pointers~~, and Crutches "  
 Upper Deck Beams & Fastenings " ~~Timbers of the~~ Frame at the Openings "  
 Lower Deck Beams & Fastenings " ~~Ditto~~ ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " ~~Copper or Y.M.~~ When put on "  
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers " Cargo and Main Hatchways Good Hatches "  
 General Observations, Opinion as to Class, &c. Good

The bottom cleaned and recoated, and the rudder pintles rebushed.  
 Now supplied with 8 manilla hawser 90 fms in length.  
 This vessel being in good and efficient condition is in my opinion eligible to remain as classed.

Committee's Minute FRIDAY 13 JAN 1884 18  
 Character assigned DRW 100A Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

No. 6393 Survey held at Glasgow Date, first Survey 28<sup>th</sup> Dec 1883 Last Survey 15<sup>th</sup> Jan 1884  
 No. in Reg. Book. 293 on the Ship "Otago" Master H. Faulkner  
 Net 993 Built at Port Glasgow When built 1869 Month 8  
 Tonnage Gross 1048 Under Dk. 899 By whom built R. Duncan & Co. Owners W. Brown  
 Port belonging to Glasgow Destined Voyage Queensland  
 If Surveyed Afloat or in Dry Dock Govan Dry Dock (State Name of Dock.)

Last Survey, No. 5939 Port of Gls Classed 19 H.L. 12, 82  
 Present Condition of the Decks Good Moulded depth 22' 5"  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, ~~Pointers~~, and Crutches "  
 Upper Deck Beams & Fastenings " ~~Timbers of the~~ Frame at the Openings "  
 Lower Deck Beams & Fastenings " ~~Ditto~~ ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " ~~Copper or Y.M. on felt~~ When put on 12, 82  
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers " Cargo and Main Hatchways Good Hatches "  
 General Observations, Opinion as to Class, &c. Good

The bottom sighted, and six sheets of new metal put on.  
 The shackle and end link of chain bobstay renewed.  
 This vessel being in good and efficient condition is in my opinion eligible to remain as classed.

Committee's Minute FRIDAY 13 JAN 1884 18  
 Character assigned DRW 19A Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

GLS148-0430