

REPORT of SURVEY for REPAIRS, &c.

2205
THURS 19 NOV 1885

No. 4205

No. in Survey held at Glasgow Date, First Survey Nov 10th 1885 Last Survey Nov 13th 1885
 Reg. Book. 88 upon the Steel Sailing Vessel Armida Master Johnston
(No. of Visits 3) YEAR. MONTH.

TONNAGE:—
 NET 1641.62 Built at Whiteinch, Glasgow By whom Barclay, Curle & Co When 1885
 GROSS 1709.92 Owners W. Latham Port belonging to Glasgow
 UNDER DEK. 1385.94 Owner's Address 49, Cathcart St. Glasgow
(if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock Afloat Name of Dock Quinn Dock Destined Voyage Melbourne
 Length of Poop 27 1/2 ft.: of Forecastle 37 ft.: of Raised Or. Deck — ft.: Moulded Depth 24 ft. 6 1/2 ins.
(with 4 1/2 ft overleap) (if these particulars are not yet recorded in the Register Book.)

Last Survey, No. 4186 Port Glasgow
 (State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard (if assigned) in salt water 5 ft. 1 ins.
 Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.) as painted on Ship } in fresh water 4 ft. 8 1/2 ins.

REPAIRS, OR EXAMINATION AS PER RULE
 The freeboard, as above assigned by the Committee, per Society's letter of 5th Inst. has been marked on the vessel's sides, examined, and found correct, in accordance with Circular 572.

PRESENT CONDITION OF THE			
Decks	Plank (Bottom) & Counter	Ceiling	Boats
Waterways	Treenails or Rivets	Rudder	Masts, Yards, &c.
Comings	Breasthooks and Stemson	Windlass & Capstan	Condition, how ascertained
Up'r Dk. Beams & Fastenings	Transoms, Pointers, & Crutches	Pumps	Sails
Low'r Dk. Beams & Fastenings	Timbers of Frame at the openings	Cement (if Iron Ship)	Anchors No. of
Planksheers	Ditto ditto at other places	Caulking of Bot'm, D'k, & Watrways	Cables
Sheerstrakes	Keelsons	Copper, or Y.M. <small>(State if on Felt.)</small>	Hawsers & Warps
Topsides	Clamps & Shelves	When put on	Standing & Running Rigging
Wales			
Engine Room Skylights	Coal Bunker, Openings, Lids, &c.	Scuppers	Cargo & Main Hatchways
			Hatches

General Observations, Opinion as to Class, &c.:
 This is a new vessel, see Glasgow first Entry Rep. No 7184

Entry Fee (if chargeable) per Scale I., Sec. 27.	£	:	:	received by me, (State if on Felt.) 188
Office Fee (if chargeable) per Scale II., Sec. 27.	£	:	:	
Survey Fee (per Section 28)	£	:	:	
Special Damage Fee (if any) (per Sec. 28)	£	:	:	
*Certificate (if required) to be sent as per margin	£	:	:	
Travelling Expenses (if chargeable)	£	:	:	
Second Surveyor's Fee (if any)	£	:	:	

Committee's Minute
 Character assigned Record freeboard
 FRIDAY 20 NOV 1885
 Surveyor to Lloyd's Register of British & Foreign Shipping.

Form No. 2 for Repairs—2004—18/85—Transfer Ink. (The Surveyors are requested not to write on or below the space for Committee's Minute.)

Insert Character precisely as in Register Book.



GL5151-0183