

REPORT of SURVEY for REPAIRS, &c.

Received in London Office,

MONDAY 20 NOV 1885

No. 4219

No. in Reg. Book. 575 on the Iron Hk. "Shakespeare" Survey held at Glasgow Date, First Survey 18th Nov^r Last Survey 24th Nov^r 1885
 (No. of Visits) Master Quen YEAR. MONTH.

TONNAGE:—
 NET 767 Built at Liverpool By whom Robt. Evans & Co. When 1876-11
 GROSS 794 Owners E. C. Friend & Co. Port belonging to Liverpool
 UNDER DK. 743 Owner's Address _____
 (if not already recorded in Appendix to Register Book.)
 If Surveyed Afloat in Dry Dock Name of Dock _____ Destined Voyage New Zealand

Length of Poop _____ ft.: of Forecastle _____ ft.: of Raised Or. Deck _____ ft.: Moulded Depth _____ ft. _____ ins.
 (if these particulars are not yet recorded in the Register Book.)
 Years assigned, if a Wood Ship. _____ Character in Register Book. _____
 Classed 7. 100 A-1.

Last Survey, No. 2121 Port Glasgow
 (State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.)
 Society's Freeboard (if assigned) _____
 in salt water _____ ft. _____ ins.
 as painted on Ship _____ in fresh water _____ ft. _____ ins.

REPAIRS, OR EXAMINATION AS PER RULE
Bottom anchor cracked, now repaired and retented at Glasgow Proving house
Test Certificate No. 1370. Test 22. 9. 1. 14
Anchor 22. 0. 16 Superintendent. E. Sealhouse
Stock 5. 0. 12 Glasgow 23rd Nov^r 1885.

PRESENT CONDITION OF THE			
Decks	Plank (Bottom) & Counter	Ceiling	Boats
Waterways	Treenails or Rivets	Rudder	Masts, Yards, &c.
Comings	Breasthooks and Stemson	Windlass & Capstan	Condition, how ascertained
Up'r Dk. Beams & Fastenings	Transoms, Pointers, & Crutches	Pumps	Sails
Low'r Dk. Beams & Fastenings	Timbers of Frame at the openings	Cement (for Iron Ship)	Anchors No. of
Planksheers	Ditto ditto at other places	Caulking of Bottom, D'k, & Watrways	Cables
Sheerstrakes	Keelsons	Copper, or V.M. (State if on Felt.)	Hawsers & Warps
Top-sides	Clamps & Shelves	When put on	Standing & Running Rigging
Wales		Scuppers	Hatches
Engine Room Slings	Coal Bunking Openings, Lids, &c.	Cargo & Main Hatchways	

Specialty at Liverpool 1885

General Observations, Opinion as to Class, &c. :
This vessel is now in good and efficient condition, and eligible in my opinion to remain as classed.

Entry Fee (if chargeable) per Scale I., Sec. 27. £ : :
 Office Fee (if chargeable) per Scale II., Sec. 27. £ : :
 Survey Fee (per Section 28) £ 1 : 0 } received by me, 28/11/1885
 Special Damage Fee (if any) (per Sec. 28) £ : :
 *Certificate (if required) to be sent as per margin £ : :
 Travelling Expenses (if chargeable) £ : :
 Second Surveyor's Fee (if any) £ : :

Geo. L. Smith
 Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute _____
 Character assigned 100 A-1

TUESDAY 1 DEC 1885



Lloyd's Register Foundation

If a Steam Ship, state whether or not a Report is also sent on the Machinery.

Insert Character precisely as in Register Book.

Form No. 2 for Repairs—2009—16/5/85—Transfer Ink. The Surveyors are requested not to write on or below the space for Committee's Minute.