

REPORT of SURVEY for REPAIRS, &c.

Received in London Office, Received 17th December 1885.

No. 4240

No. in Survey held at Reg. Book.

0120 on the

Glasgow
Iron S.S. "Cipero"

Date, First Survey 5th Dec 1885

(No. of Visits 3)

Last Survey 11 Dec 1885
Master Copeland
YEAR. MONTH.

TONNAGE:—

NET 908

GROSS 1419

UNDER DK. 1063

Built at

Owners

Owner's Address

(if not already recorded in Appendix to Register Book.)

By whom

When 1879

Port belonging to

If Surveyed Afloat or in Dry Dock

Name of Dock

Destined Voyage

Length of Poop

ft.: of Forecastle

ft.: of Raised Or. Deck

ft.: Moulded Depth

ft.

ins.

(if these particulars are not yet recorded in the Register Book.)

Classed

100 A.1

Last Survey, No.

6820 Port

Gls

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.)

Society's Freeboard (if assigned)

in salt water

in fresh water

1 ft. 10 1/2 ins.

2 ft. 4 ins.

REPAIRS OR EXAMINATION AS PER RULE

The freeboard as above, assigned by the Committee as per Secys. letter of 3rd Inst. has been marked on the sides of the vessel, examined and found correct. In accordance with the instructions contained in the Secys letter of above date, an efficient platform has been fitted over the well, as a means of access for the crew to get from the bridge to their berths in bad weather. Solid hatches 3" in thickness have also been fitted in the hatchways in well.

PRESENT CONDITION OF THE

Decks
Waterways
Bomings
Up'r Dk. Beams & Fastenings
Low'r Dk. Beams & Fastenings
Planksheers
Sheerstrakes
Topsides
Wales

Plank (Bottom) & Counter

Treenails or Rivets

Breasthooks and Stemson

Transoms, Pointers, & Crutches

Timbers of Frame at the openings

Ditto ditto at other places

Keelsons

Clamps & Shelves

Ceiling

Rudder

Windlass & Capstan

Pumps

Cement (if Iron Ship)

Caulking of Bot'm, D'k, & Watrways

Copper, or Y.M.

(State if on Felt.)

When put on

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors

No. of

Cables

Hawsers & Warps

Standing & Running Rigging

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo & Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.:

The above is reported for the information of the Committee.

Entry Fee (if chargeable) per Scale I., Sec. 27.
Office Fee (if chargeable) per Scale II., Sec. 27.
Survey Fee (per Section 28)
Special Damage Fee (if any) (per Sec. 28)
Certificate (if required) to be sent as per margin
Travelling Expenses (if chargeable)
Second Surveyor's Fee (if any)

received by me, 188

Committee's Minute
Character assigned

FRIDAY 18 DEC 1885

Chas. Edwards
Surveyor to Lloyd's Register of British & Foreign Shipping.