

REPORT of SURVEY for REPAIRS, &c.

No. 4860

Port of Glasgow

Received in London Office THURS 24 MARCH 1887

No. in Reg. Book.

Survey held at

Glasgow

Date, First Survey

Last Survey

11th March 1887

(No. of Visits)

One

Master

Smith

YEAR.

MONTH.

TONNAGE:—

NET

1069

GROSS

1298

UNDER DK.

1298

Built at

Glasgow

By whom

Lo. & Glas. Co.

When

1871-3

Owners

Robertson & Mac

Port belonging to

London

Owner's Address

(if not already recorded in Appendix to Register Book.)

If Surveyed in Dry Dock

Name of Dock

Govan Dry Dock

Destined Voyage

S. America

Length of Poop

ft.: of Forecastle

ft.: of Raised Qr. Deck

ft.: Moulded Depth

ft.

ins.

(if these particulars are not yet recorded in the Register Book.)

Years assigned, if a Wood Ship.

Character in Register Book.

Classed

100A-1

Last Survey, No.

4662

Port

Gls

S.S. Lo. No. 3 - '82

10- '86

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.)

Society's Freeboard (if assigned)

in Summer

ft.

ins.

as painted on Ship

in Winter

ft.

ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Vessel placed in dry dock, bottom cleaned and treated. Captain's attention was drawn to the S.S. No. 1 not yet having been completed, and the Owners were written to; the Owners' reply stating they will proceed with the survey on the return of the vessel is attached hereto.

For what has already been done of the special survey, see Glasgow Report No. 7662.

PRESENT CONDITION OF THE

| | | | | | | | |
|---|---|------------------------------------|----------|-------------------------------------|----------|----------------------------|---------------------|
| Deck | good | Plating (Bottom) & Counter | good | Ceiling | good | Boats | good |
| Waterways | " | Seamstitching or Rivets | " | Rudder | " | Masts, Yards, &c. | " |
| Comings | " | Breasthooks and Stems | not seen | Windlass & Capstan | " | Condition, how ascertained | from arc. |
| Up'r Dk. Beams & Fastenings | " | Transoms, Portainers, & Grutches | " | Pumps | " | Sails | good |
| Low'r Dk. Beams & Fastenings | " | Stiffness of Frame at the openings | good | Cement (if Iron Ship) | not seen | Anchor | No. of 3/2. 12. 2K. |
| Stanchions | " | ditto ditto at other places | not seen | Caulking of Bot'm, D'k, & Wat'rways | good | Cables | Plated 5/2 complete |
| Sheerstrakes | " | Keelsons | " | Support, or T.M. (State if any) | " | Hawsers & Warps | good |
| Topsides | " | Clamps & Shells | " | Wharves | " | Standing & Running Rigging | " |
| Engine Room Skylights | good | Coal Bunker, Openings, Lids, &c. | good | Scuppers | good | Cargo & Main Hatchways | good |
| General Observations, Opinion as to Class, Recommendation, &c.: | This vessel is now in good condition, and the Owners' proposal to proceed with the survey on her return, is worthy the favourable consideration of the Committee. | | | | | | |

Entry Fee (if chargeable) per Scale I., Sec. 27...
Office Fee (if chargeable) per Scale II., Sec. 27...
Survey Fee (per Section 28)...
Special on Damage, Fee (if any) (per Sec. 28)...
Certificate (if required) to be sent as per margin...
Travelling Expenses (if chargeable)...
Second Surveyor's Fee (if any)...

Fees received by me, 188

Chas. Forth

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

FRIDAY 25 MARCH 1887

Character assigned

Note: Vessel