

REPORT of SURVEY for REPAIRS, &c.

No. 8190

Port of Glasgow

Received in London Office,

SAT 29 OCT 1887

No. in Reg. Book.

Survey held at Troon

Date, First Survey 24th Oct

Last Survey 20th Oct

1887

(No. of Visits)

2

Master

W. McKinlay

YEAR.

MONTH.

TONNAGE:-

NET 500

GROSS 744

UNDER DK. 614

Built at

Dundee

By whom

Parce Bros

When

1882 - 8

Owners

Warkman Clark & Co Ltd

Port belonging to

Belfast

Owner's Address

(if not already recorded in Appendix to Register Book.)

If Surveyed

Afloat or in Dry Dock

Dry

Name of Dock

Troon

Destined Voyage

Bayonne

Length of Poop

ft.: of Forecastle

ft.: of Raised Or. Deck

ft.: Moulded Depth

ft. ins.

(if these particulars are not yet recorded in the Register Book.)

Classed

Years assigned, if a Wood Ship.

Character in Register Book.

Last Survey, No.

648

Port

Cardiff

00 Bda. 10. 85.

100 A. 1. 9. 85

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.)

in Summer

ft. ins.

in Winter

ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Periodical Survey

Sighted bottom, scraped & repainted. New Rudder fitted. Steering gear repaired. Two pillars & two ladder stanchions repaired. Two Couls to Stoker hold ventilators renewed. Sounding pipe to fore peak tank repaired. Drain top mast renewed. Angles to hold beam at fore end of after body partly renewed. For raising Engine skylight - 18 plates now fitted above previous covers.

PRESENT CONDITION OF THE

Decks	food	Plating	food	Ceiling	food	Boats	food
Waterways	"	Plank (Bottom) & Counter	"	Rudder	"	Masts, Yards, &c.	"
Comings	"	Transoms & Rivets	"	Windlass & Capstan	"	Condition, how ascertained	Mondecar
Up'r Dk. Beams & Fastenings	"	Breasthooks and Stemson	"	Pumps	"	Sails	food
Low'r Dk. Beams & Fastenings	"	Transoms, Pointers, & Crutches	"	Cement (if Iron Ship)	"	Anchors	No. of 3 B. 15. 24.
Planksheers	"	Timbers of Frame at the openings	"	Caulking of Bot'm, D'k, & Watrways	"	Cables	"
Sheerstrakes	"	Ditto ditto at other places	"	Copper, or Y.M.	"	Hawsers & Warps	"
Topsides	"	Keelsons	"	(State if on Fell.)	"	Standing & Running Rigging	"
Wales	"	Clamps & Shelves	"	When put on	"	Hatches	food
Engine Room Skylights	"	Coal Bunker, Openings, Lids, &c.	food	Scuppers	food	Cargo & Main Hatchways	food

General Observations, Opinion as to Class, Recommendation, &c.:

This vessel appears to be in good and efficient condition and is in my opinion eligible to remain as classed

Entry Fee (if chargeable) per Scale I., Sec. 27...	£	✓	:	:	:
Office Fee (if chargeable) per Scale II., Sec. 27...	£	✓	:	:	:
Survey Fee (per Section 28)	£	1	:	1	:
Special on Damage, Fee (if any) (per Sec. 28)...	£	✓	:	:	:
*Certificate (if required) to be sent as per margin	£	✓	:	:	:
Travelling Expenses (if chargeable)	£	1	:	✓	:
Second Surveyor's Fee (if any)	£	✓	:	:	:

Fees at 1/6 received by me 4/11/1887


Committee's Minute

TUESDAY 1 NOV 1887

Character assigned

100 A. 1. 9. 85

Surveyor to Lloyd's Register of British & Foreign Shipping.



Lloyd's Register Foundation