

REPORT of SURVEY for REPAIRS, &c.

No. 8223

Port of Glasgow

Received in London Office,

MONDAY 21 NOV 1887

No. in Reg. Book. Survey held at Glasgow Date, First Survey 17th Nov 1887 Last Survey 17th Nov 1887
 on the "Clan Ranald" (No. of Visits) Master J. Millar

TONNAGE:—
 NET 1339 Built at Dumbarton By whom A. McMillan
 GROSS 2068 Owners Cargill & Co. Port belonging to Glasgow
 UNDER DECK 1918 Owner's Address (if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock Dry Name of Dock Henderson's Destined Voyage Natal.

Length of Poop ft.: of Forecastle ft.: of Raised Or. Deck ft.: Moulded Depth ft. ins.
 (if these particulars are not yet recorded in the Register Book.)

Last Survey, No. 4996 Port Glasgow

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE, FOR Damage & defects this decay.
 The bulwarks each side in front of Bridge House, indented & fractured, set fair & covering pieces fitted inside. Forecastle plating above funnel damaged port side, now repaired. Guard Stations from bows to stern. Two anchor davits renewed. About 300 ft of D.K. plating renewed with G.Pine & the whole recaulked, where necessary. Rudder finlets rebushed. The outside generally made of nos 1.2 & 5 holds now repainted.

PRESENT CONDITION OF THE		Plating		Ceiling		Boats	
Decks	good	Blank (Bottom) & Counter	good	Rudder	good	Masts, Yards, &c.	good
Waterways	✓	Treenails or Rivets	✓	Windlass & Capstan	✓	Condition, how ascertained	From D.K.
Comings	✓	Breasthooks and Stemson	✓	Pumps	✓	Sails	good
Up'r Dk. Beams & Fastenings	✓	Transoms, Pointers, & Crutches	✓	Cement (if Iron Ship)	✓	Anchors	No. of 3 M. B. D. K.
Low'r Dk. Beams & Fastenings	✓	Timbers of Frame at the openings	✓	Caulking of Bot'm, D'k, & Wat'rways	✓	Cables	Partisan
Planksheers	✓	Ditto ditto at other places	✓	Copper, or Y.M.	✓	Hawsers & Warps	✓
Sheerstrakes	✓	Keelsons	✓	(State if on Felt.)	✓	Standing & Running Rigging	✓
Topsides	✓	Clamps & Shelves	✓	When put on	✓		
Wales	✓						
Engine Room Skylights	✓	Coal Bunker, Openings, Lids, &c.	good	Scuppers	good	Cargo & Main Hatchways	good
						Hatches	good

General Observations, Opinion as to Class, Recommendation, &c.:
 This vessel appears to be in good condition and in my opinion eligible to remain as classed.

Entry Fee (if chargeable) per Scale I., Sec. 27... £ : :
 Office Fee (if chargeable) per Scale II., Sec. 27... £ : :
 Survey Fee (per Section 28) £ 1 : 1 :
 Special on Damage, Fee (if any) (per Sec. 28) £ : :
 *Certificate (if required) to be sent as per margin £ : :
 Travelling Expenses (if chargeable) £ : :
 Second Surveyor's Fee (if any) £ : :
 Committee's Minute
 Character assigned

Fees received by me, 19/11/87
 Surveyor to Lloyd's Register of British & Foreign Shipping.

TUESDAY 22 NOV 1887

100