

REPORT of SURVEY for REPAIRS, &c.

8434
29 MAR 88

No. 8434 Date of Writing Report 188 Port of Glasgow Received in London Office, 29 MAR 88
No. in Reg. Book. Survey held at Glasgow Date, First Survey 8th March Last Survey 23rd March 1888
(No. of Visits)

719 on the "S. O. Kerrymore" Master John Skirling
YEAR. MONTH.

TONNAGE:— NET 528 Built at Belfast By whom Portman, Clark & Co When 1882-10
GROSS 994 Owners Clyde Shipping Co Port belonging to Glasgow
GROSS DECK 789 Owner's Address Glasgow

If Surveyed Afloat or in Dry Dock Ship Name of Dock Ayr Dock Destined Voyage Coasting
Length of Poop ft.: of Forecastle ft.: of Raised Or. Deck ft.: Moulded Depth ft. ins.
(If these particulars are not yet recorded in the Register Book.)

Classed 100A1
Last Survey, No. 8293 Port GLE
S. O. Kerrymore - 87
1888

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard (if assigned) in Summer ft. ins.
Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.) as painted on Ship in Winter ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR of Damage Caused by stranding.
The stem frame broken at three places viz at two places in sole between the posts & at rudder post about 18 ins from heel. The whole cut out a new sole piece welded as shown on the Forge Inspector's report attached.
Bottom recoated. A shoe plate fitted for 16 ft. to keel aft of 1/2" steel plate.

PRESENT CONDITION OF THE		Planking		Ceiling		Boats	
Decks	good	Plank (Bottom) & Counter	good		good		good
Waterways	✓	Treenails or Rivets	✓	Rudder	✓	Masts, Yards, &c.	✓
Comings	✓	Breasthooks and Stemson	✓	Windlass & Capstan	✓	Condition, how ascertained	found
Up'r Dk. Beams & Fastenings	✓	Transoms, Pointers, & Crutches	✓	Pumps	✓	Sails	good
Low'r Dk. Beams & Fastenings	✓	Timbers of Frame at the opening	✓	Cement (if Iron Ship)	✓	Anchors No. of	2 R. 15. 24
Planksheers	✓	Ditto ditto at other places	✓	Caulking of Bot'm, D'k, & Watrways	✓	Cables	P.O.
Sheerstrakes	✓	Keelsons	✓	Copper, or Y.M. (State if on Felt.)	✓	Hawsers & Warps	✓
Topsides	✓	Clamps & Shelves	✓	When put on	✓	Standing & Running Rigging	✓
Wales	✓					Hatches	✓
Engine Room Skylights	✓	Coal Bunker, Openings, Lids, &c.	good	Scuppers	good	Cargo & Main Hatchways	good

General Observations, Opinion as to Class, Recommendation, &c. :
This vessel is now in good condition in my opinion eligible to remain as classed

Entry Fee (if chargeable) per Scale I., Sec. 27...	£	:	:
Office Fee (if chargeable) per Scale II., Sec. 27...	£	:	:
Survey Fee (per Section 28)	£	2	2
Special on Damage, Fee (if any) (per Sec. 28)...	£	:	:
*Certificate (if required) to be sent as per margin	£	:	:
Travelling Expenses (if chargeable)	£	:	:
Second Surveyor's Fee (if any)	£	:	:

Fees applied for, 24/3 1888
Received by me, 31/3 1888
J. Dawkins
Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute TUES 3 APRIL 1888
Character assigned 100A1
dry 88

Form No. 2 for Repairs—1000. The Surveyors are requested not to write on or above.

Insert Character precisely as in Register Book.

