

Report of Survey for Repairs, &c., of Engines & Boilers.

8439

No. 8439

Port of Glasgow (Received at London Office,

5 APR 88

No. in Survey held at Glasgow Date, first Survey and Last Survey 27th March 1888
 Reg. Book. 341 on the Machinery of the S. S. "Carthaginians" (Number of Visits One)
Year Month

Tonnage, Gross 4214 Built at Glasgow When built 1884. 10
 Ditto, Net 2755 Owners J & A. Allan Port belonging to Glasgow
 Diameter of Cylinders 51 3/8" Engines made by J & J. Thomson When made 1884
 Length of Stroke 54" Boilers made by J & J. Thomson When made 1884
 Pressure of Steam 80 lbs. If Surveyed Afloat or in Dry Dock Govan Dk Character in Register Book.
 Registered Horse Power 520 (State Name of Dock.) Classed 700 A 1
 Last Survey No. 2. 87. T.L.M.C. 12. 84.

Particulars of Repairs and Examination

(State clearly the cause of Repairs if any, and in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.)

Docking Survey.

When the vessel was in drydock the propellers and fastenings were examined and found in good order.
All sea connections examined externally and found in good order.

General Observations, Opinion, and Recommendation:— As far as can be ascertained by above survey this vessels machinery appears to be in good working order and is in my opinion eligible to remain as classed.
(State clearly what alteration, if any, is suggested to be made in the existing notification of the vessel's machinery in the Register Book, consequent upon this survey.)


Office or Registration Fee (per Sec. 27) £ : :
 Survey Fee (per Section 28) £ : :
 Special on Damage Fee (per Section 28) £ : :
 *Certificate (if required) to be sent as per margin.. £ : :
 Travelling Expenses (if chargeable)..... £ : :

received by me,
188

John Sanderson
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute FRIDAY 6 APRIL 1888

Assigned



Be particular to state if a Report is also sent on the Hull of the ship.

Form No. 9... (The Surveyors are requested not to write on or below the space for Committee's Minute.)

Insert Character of Ship and Machinery precisely as in the Register Book.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

It is submitted that this vessel
is eligible to remain as classed

843988

W.P.
3/4/88



© 2019
Lloyd's Register
Foundation

Vertical text on the right edge of the page, possibly a stamp or reference number.