

REPORT of SURVEY for REPAIRS, &c.

8540 Date of Writing Report 188 Port of Glasgow Received in London Office, 23 MAY. 88

in Survey held at Glasgow Date, First Survey and Last Survey 18th May 1888

Book. on the Iron Steamer "Glenurath" Master Anderson

TONNAGE:— 1109 Built at Newcastle By whom Palmerston When 1879-1880

ET 1785 Owners Lindsay, Grace & Co Port belonging to Leith

ROSS 1538 Owner's Address (if not already recorded in Appendix to Register Book.)

UNDER DK 1538 Surveyed Afloat or in Dry Dock Dry Name of Dock Govan Destined Voyage Black Sea

Length of Poop ft. of Forecastle ft. of Raised Or. Deck ft. of Moulded Depth ft. ins.

Classed 100 A1

Last Survey, No. 32425 Port Rio

to clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard (if assigned) in Summer ft. ins.

Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials as painted on Ship in Winter ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Annual Survey.

Bottom Examined, cleaned & repainted.

To replace articles lost the following have now been put on board.

Art. No	Height	Cost
Bow anchor 10897	30" 0" 11 1/2	18" 14" 1" 11 1/2
And link cable 9615	15" 8" 1 1/2	55 1/2 & 77 1/2

Noted by E R Smith Tipton.

PRESENT CONDITION OF THE		Plank		Ceiling		Boats	
Decks	ford	Plank (Bottom) & Counter	ford	Rudder	ford	Masts, Yards, &c.	ford
Waterways	✓	Trunnions or Rivets	✓	Windlass & Capstan	✓	Condition, how ascertained	ford
Comings	✓	Breasthooks and Stemson	✓	Pumps	✓	Sails	ford
Up'r Dk. Beams & Fastenings	✓	Transoms, Pointers, & Crutches	✓	Cement (if Iron Ship)	✓	Anchors No. of	3 B. 15 2 K.
Low'r Dk. Beams & Fastenings	✓	Timbers of Frame at the opening	✓	Caulking of Bot'm, D'k, & Watrways	✓	Cables	✓
Plank sheers	✓	Ditto ditto at other places	✓	Copper, or Y.M.	✓	Hawsers & Warps	✓
Sheerstrakes	✓	Keelsons	✓	(State if on Felt.)	✓	Standing & Running Rigging	✓
Topsides	✓	Clamps & Shelves	✓	When put on	✓	Hatches	✓
Wales	✓						
Engine Room Skylights	✓	Coal Bunker, Openings, Lids, &c.	ford	Scuppers	ford	Cargo & Main Hatchways	ford

General Observations, Opinion as to Class, Recommendation, &c.:

This vessel appears to be in good Condition and in my opinion eligible to remain as classed

Entry Fee (if chargeable) per Scale I., Sec. 27...	£		
Office Fee (if chargeable) per Scale II., Sec. 27...	£		
Survey Fee (per Section 28)	£		
Special on Damage, Fee (if any) (per Sec. 28)	£		
Certificate (if required) to be sent as per margin	£		
Travelling Expenses (if chargeable)	£		
Second Surveyor's Fee (if any)	£		

Fees applied for,

188

Received by me,

188

Committee's Minute

FRI 25 MAY 88

Character assigned

100 A1

Surveyor to Lloyd's Register of British & Foreign Shipping.



Lloyd's Register Foundation