

# REPORT of SURVEY for REPAIRS, &c.

No. 8434 Date of Writing Report 22<sup>nd</sup> August 1888 Port of

No. in Reg. Book. 552 Survey held at Glasgow Date, First Survey 26<sup>th</sup> July Last Survey 16<sup>th</sup> August 1888

on the Steel Screw Steamer "Prince Alfred" Master Day Whitley

TONNAGE NET 27 GROSS 100 UNDER DECK 100 Built at Hull By whom Vulcan S. & Co. When 1883 3

Owners Ardrossan Shipping Co. Port belonging to Montrose London

Owner's Address (if not already recorded in Appendix to Register Book.) Ship John Ingham

If Surveyed Afloat or in Dry Dock Dock Name of Dock John Ingham Destined Voyage

Length of Poop ft. of Forecastle ft. of Raised Or. Deck ft. of Moulded Depth ft. ins. (if these particulars are not yet recorded in the Register Book.)

Classed 100 A 1 7,87

Last Survey, No. 8083 Port Glasgow

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE, FOR Annual Survey and alterations.

The Vessel placed upon the Slip bottom cleaned and examined, and coated. One butt of garboard stake on starboard side amidships caulked. The whole of cement on bottom throughout removed, and renewed, floors scaled and cement washed. Inside of Vessel painted. Fore Hatchway enlarged to 10ft 0in x 7ft 8in with new deck tie plates and coaming plates; Ceiling in greater part renewed. A new Elm main Rail fitted.

PRESENT CONDITION OF THE	Rating	Plank (Bottom) & Counter	Ceiling	Boats
Decks	Good	Good	Good	Good
Waterways	do.	do.	do.	do.
Comings	do.	do.	do.	do.
Up'r Dk. Beams & Fastenings	do.	do.	do.	do.
Low'r Dk. Beams & Fastenings	do.	do.	do.	do.
Plank sheers	Good	do.	do.	do.
Sheerstrakes	Good	do.	do.	do.
Top-sides	do.	do.	do.	do.
Wales	do.	do.	do.	do.
Engine Room Skylights	Good	do.	do.	do.
Coal Bunker, Openings, Lids, &c.	Good	do.	do.	do.
Scuppers	Good	do.	do.	do.
Cargo & Main Hatchways	Good	do.	do.	do.
Hatches	Good	do.	do.	do.

General Observations, Opinion as to Class, Recommendation, &c.:

This Vessel is now in good and efficient condition and eligible in my opinion to remain as classed.

Entry Fee (if chargeable) per Scale I., Sec. 27...	£	:	:
Office Fee (if chargeable) per Scale II., Sec. 27...	£	:	:
Survey Fee (per Section 28) ...	£	2	2
Special on Damage, Fee (if any) (per Sec. 28) ...	£	:	:
*Certificate (if required) to be sent per margin	£	:	2
Travelling Expenses (if chargeable) ...	£	:	:
Second Surveyor's Fee (if any) ...	£	:	:

Fees applied for, 16/8/1888 Received by me, 24/8/1888

W. J. Lowther, Dutton Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute FRIDAY 24 AUGUST 1888

Character assigned 100 A 1 + dm 6 8/88

HULL CERTIFICATE WRITTEN. 25/8/88

ROBERT EDMUND TAYLOR & SON, Commercial Steam Printers, 19, Old Street, Goswell Road, London.

Lloyd's Register Foundation