

# REPORT of SURVEY for REPAIRS, &c.

No. 8461. Date of Writing Report 188 Port of Glasgow Received in London Office, THURS 6 SEPT 1888  
 No. in Survey held at Glasgow Date, First Survey 24<sup>th</sup> Augt Last Survey 1<sup>st</sup> Sept 1888  
 g. Book. 387 on the Iron Ship *hinchfoushrie* (No. of Visits four) Master *Stott*

TONNAGE:— NET 1354 Built at Port Glasgow By whom *H. Murray & Co* When 1877-6  
 GROSS 1425 Owners *J. Lawrie* Port belonging to Glasgow  
 UNDER DK. 1289 Owner's Address (if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock *Afloat* Name of Dock *Queens* Destined Voyage *Brisbane*  
 Length of Poop ft.: of Forecastle ft.: of Raised Or. Deck ft.: Moulded Depth ft. ins.  
 (if these particulars are not yet recorded in the Register Book.)

Last Survey, No. 4892 Port *Bristol* Classified *S. Shew 100 9.86*  
 (State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard in Summer 4 ft. 6 1/2 ins.  
 Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials (if assigned) as painted on Ship in Winter 4 ft. 6 1/2 ins.  
 of any letters respecting this case.

REPAIRS, OR EXAMINATION AS PER RULE, FOR *Completion of survey held at Bristol*

*Now put on board*  
 75 Steel hammer 3 1/2  
 18 Drumma 12  
 75 steel hammer 2  
 90 Drumma 5  
 90 — — 4 1/2  
*R.S. Hewalls*

*The freeboard has been correctly marked. already in book*

*Returned for production of Steel hammer test certificate*  
*5/9/88*  
*B.*

## PRESENT CONDITION OF THE

Decks	Plank (Bottom) & Counter	Ceiling	Boats
Waterways	Treenails or Rivets	Rudder	Masts, Yards, &c.
Comings	Breasthooks and Stemson	Windlass & Capstan	Condition, how ascertained
Up'r Dk. Beams & Fastenings	Transoms, Pointers, & Crutches	Pumps	Sails
Low'r Dk. Beams & Fastenings	Timbers of Frame at the opening	Caulk'g of Bot'm, D'k, & Watrways	Anchors No. of
Planksheers	Ditto ditto at other places	Copper, or Y.M. (State if on Felt.)	Cables
Sheerstrakes	Keelsons	When put on	Hawsers & Warps
Topsides	Clamps & Shelves		Standing & Running Rigging
Wales			
Engine Room Skylights	Coal Bunker, Openings, Lids, &c.	Scuppers	Cargo & Main Hatchways
			Hatches

## General Observations, Opinion as to Class, Recommendation, &c.:

*The hawsers detailed above have now been put on board in completion of vessel's equipment*

Entry Fee (if chargeable) per Scale I., Sec. 27...	£	:	:	Fees applied for,
Office Fee (if chargeable) per Scale II., Sec. 27...	£	:	:	188
Survey Fee (per Section 28) .....	£	:	:	
Special on Damage, Fee (if any) (per Sec. 28)....	£	:	:	
*Certificate (if required) to be sent as per margin	£	:	:	Received by me,
Travelling Expenses (if chargeable) .....	£	:	:	188
Second Surveyor's Fee (if any) .....	£	:	:	

Committee's Minute

FRIDAY 7 SEPT 1888

Character assigned

*As now - see Bns. 4892*

Surveyor to Lloyd's Register of British & Foreign Shipping.