

REPORT of SURVEY for REPAIRS, &c.

No. 8772. Date of Writing Report 8th Sept. 1888 Port of Glasgow Received in London Office, 17 SEP 88
 No. in Survey held at Dyr Date, First Survey 28th Aug Last Survey 5th Sept. 1888
 g. Book. (No. of Visits) three

607 on the S.S. "Amanda" Master W. Windows 1886-88
 TONNAGE:— Built at Greenock By whom Caird & Co. When 1871 11
 NET 192 Owners Shearer Bros. Port belonging to Greenock
 GROSS 353
 UNDER DK. 345 Owner's Address

If Surveyed Afloat or in Dry Dock Afloat Name of Dock Dyr Harbour Destined Voyage Baltic
 Length of Poop ft.: of Forecastle ft.: of Raised Or. Deck ft.: Moulded Depth ft. ins.
 (if these particulars are not yet recorded in the Register Book.)

Last Survey, No. 3392 Port Greenock S.S. Act. 9:3-11, 82. S.S. Act. 9:1-85. 91 A. 1, 88
 (State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard in Summer ft. ins.
 Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials (if assigned) as painted on Ship in Winter 4 M 1585
 of any letters respecting this case.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Completion of Special Survey 9:3.
 The upper deck sheathed or doubled with pitch pine 2" thick and well secured with galvanized screws; thus completing the S.S. 9:3. See Greenock Report 9:9441 herewith returned.

PRESENT CONDITION OF THE	to	Plank (Bottom) & Counter	Ceiling	Boats
Decks	Wood	Wood	Wood	Wood
Hatchways		Iron or Rivets	Rudder	Masts, Yards, &c.
Stowings		Breasthooks and Stemson	Windlass & Capstan	Condition, how ascertained From deck
Upper Dk. Beams & Fastenings		Transoms, Decks, & Crutches	Pumps	Sails Wood
Lower Dk. Beams & Fastenings		Timbers of Frame at the opening	Cement (if Iron Ship)	Anchor No. of 3 B. 1 S. 1 K.
Keelsons		Ditto ditto at other places	Caulking of Bot'm, D'k, & Watrways	Cables Stated to be complete
Strakes		Keelsons	Copper, or Y.M. (State if on Felt.)	Hawsers & Warps Wood
Staircases		Clamps & Shelves	When put on	Standing & Running Rigging
Engine Room Skylights		Coal Bunker, Openings, Lids, &c.	Scuppers Wood	Cargo & Main Hatchways Wood
Hatches				Hatches

General Observations, Opinion as to Class, Recommendation, &c.:
 This vessel appears to be in good and efficient condition, is in my opinion eligible to remain as classed, and to be noted in the Register Book S.S. 9:3-88

Entry Fee (if chargeable) per Scale I., Sec. 27...	£	:	:	Fees applied for, 10/9/ 1888 Received by me, 12/9/ 1888 Jastwright
Office Fee (if chargeable) per Scale II., Sec. 27...	£	—	✓	
Survey Fee (per Section 28)	£	2	2	
Special on Damage, Fee (if any) (per Sec. 28)	£	—	✓	
*Certificate (if required) to be sent as per margin	£	—	5	
Travelling Expenses (if chargeable)	£	✓	18	
Second Surveyor's Fee (if any)	£	—	✓	

J. Thomson
 Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute FRIDAY 14 SEPT 1888
 Character assigned 90A1 S.S. Act. 9:3-1, 88 Dd 88
 LMC 10, 87
 Lloyd's Register Foundation
 ROBERT EDMUND TAYLOR & SON, Commercial Steam Printers, 19, Old Street, Goswell Road, London.
 GCS156-0166