

REPORT of SURVEY for REPAIRS, &c.

No. **9090** Date of Writing Report **188** Port of **Glasgow** Received in London Office **MON 1 APRIL 1889**
 No. in Reg. Book **210** Survey held at **Glasgow** Date, First Survey **26th March** Last Survey **28th March 1889**
 on the **Iron S.S. Behera** (No. of Visits **2**) Master **McDonald**

TONNAGE:—
 NET **829** Built at **Newcastle** By whom **Marshall Bros.** When **1864**
 GROSS **1384** Owners **MacLay & Mesdigne** Port belonging to **Glasgow**
 UNDER DECK **1366** Owner's Address _____
 If Surveyed Afloat or in Dry Dock **for a day** of Dock _____ Destined Voyage **Patrol**
 Length of Poop _____ ft.: of Forecastle _____ ft.: of Raised Or. Deck _____ ft.: Moulded Depth _____ ft. _____ ins.
(if these particulars are not yet recorded in the Register Book.)

Last Survey, No. **8944** Port **Glasgow** Classed **S.O. 13. 4. 79**
(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.)
 in Summer _____ ft. _____ ins.
 as painted on Ship in Winter _____ ft. _____ ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR **Repainting &c.**
The bottom examined scraped & repainted

| PRESENT CONDITION OF THE | Plating | Food | Food | Food | Food |
|------------------------------|----------------------------------|------|------|------|------|
| Decks | Plank (Bottom) & Counter | ✓ | ✓ | ✓ | ✓ |
| Waterways | Tween-decks or Rivets | ✓ | ✓ | ✓ | ✓ |
| Comings | Breasthooks and Stemson | ✓ | ✓ | ✓ | ✓ |
| Up'r Dk. Beams & Fastenings | Transoms, Pointers, & Crutches | ✓ | ✓ | ✓ | ✓ |
| Low'r Dk. Beams & Fastenings | Timbers of Frame at the opening | ✓ | ✓ | ✓ | ✓ |
| Planksheers | Ditto ditto at other places | ✓ | ✓ | ✓ | ✓ |
| Sheerstrakes | Keelsons | ✓ | ✓ | ✓ | ✓ |
| Topsides | Clamps & Shelves | ✓ | ✓ | ✓ | ✓ |
| Wales | | ✓ | ✓ | ✓ | ✓ |
| Engine Room Skylights | Coal Bunker, Openings, Lids, &c. | ✓ | ✓ | ✓ | ✓ |
| | Scuppers | ✓ | ✓ | ✓ | ✓ |
| | Cargo & Main Hatchways | ✓ | ✓ | ✓ | ✓ |
| | Hatches | ✓ | ✓ | ✓ | ✓ |

General Observations, Opinion as to Class, Recommendation, &c.:
This vessel is in good condition and in my opinion eligible to remain as classed

| | | | |
|---|---|---|---|
| Entry Fee (if chargeable) per Scale I., Sec. 27... | £ | : | : |
| Office Fee (if chargeable) per Scale II., Sec. 27... | £ | : | : |
| Survey Fee (per Section 28) | £ | : | : |
| Special on Damage, Fee (if any) (per Sec. 28) | £ | : | : |
| Certificate (if required) to be sent as per regulations | £ | : | : |
| Travelling Expenses (if chargeable) | £ | : | : |
| Second Surveyor's Fee (if any) | £ | : | : |

Fees applied for, **188**
 Received by me, **188**
J. R. Cantor
 Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute **TUES 2 APRIL 1889**
 Character assigned **B**

