

REPORT of SURVEY for REPAIRS, &c.

No. 9141 Date of Writing Report 1888 Port of Glasgow Received in London Office.
 No. in Survey held at Glasgow Date, First Survey and Last Survey 18th July 1888
 Reg. Book. 300 on the Iron Bt Thornliebank (No. of Visits One) Master Erskine

TONNAGE:—
 NET 1405 Built at Glasgow By whom Russell & Co When 1886 - 11
 GROSS 1492 Owners A. Meir & Co Port belonging to Glasgow
 UNDER DEK 1353 Owners' Address (if not already recorded in Appendix to Register Book.)
 Afloat or in Dry Dock Afloat Name of Dock James Destined Voyage _____
 of Poop _____ ft.: of Forecastle _____ ft.: of Raised Or. Deck _____ ft.: Moulded Depth _____ ft. _____ ins.
(if these particulars are not yet recorded in the Register Book.)

Last Survey, No. 9544 Port GWRK Classed 100A1
12.86
 (State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case. 17th July 1888 14th May 1889)
 Society's Freeboard } in Summer ft. _____ ins. _____
 (if assigned) }
 as painted on Ship } in Winter ft. _____ ins. _____

REPAIRS, OR EXAMINATION AS PER RULE, FOR Completion of Equipment.
In lieu of broken dramilla spring to steel tow line the following put on board. Fall in 30 - 13 dramilla.

PRESENT CONDITION OF THE			
Decks	Plank (Bottom) & Counter	Ceiling	Boats
Waterways	Treenails or Rivets	Rudder	Masts, Yards, &c.
Comings	Breasthooks & Stemson	Windlass & Capstan	Condition, how ascertained
Up'r Dk. Beams & Fastenings	Transoms, Pointers, & Crutches	Pumps	Sails
Low'r Dk. Beams & Fastenings	Timbers of Frame at the openings	Cement (if Iron Ship)	Anchor No. of
Keelsons	Ditto ditto at other places	Caulking of Bottom, &c. at _____	Cables
Deckstrakes	Keelsons	Copper, or T.M. (State if on Felt.)	Hawsers & Warps
Stanchions	Clamps & Shelves	When put on	Standing & Running Rigging
Line Room Skylights	Coal Bunker, Openings, Lids, &c.	Scuppers	Cargo & Main Hatchways
			Hatches

General Observations, Opinion as to Class, Recommendation, &c. :
In completion of Equipment. The hawsers mentioned above has been supplied.

Entry Fee (if chargeable) per Scale I., Sec. 27...	£	:	:	Fees applied for, 188
Office Fee (if chargeable) per Scale II., Sec. 27...	£	:	:	
Survey Fee (per Section 23)	£	:	:	
Special on Damage, Fee (if any) (per Sec. 23)	£	:	:	
*Certificate (if required) to be sent as per margin	£	:	:	
Travelling Expenses (if chargeable)	£	:	:	
Second Surveyor's Fee (if any)	£	:	:	Received by me, 188

Committee's Minute FRIDAY 17 MAY 1889
 Character assigned 100A1 on hulk Rep no 9544
 Surveyor to Lloyd's Register of British & Foreign Shipping. J. G. Cantano

Form No. 2 for Repairs—1000—147/88.—Transfer Int.—T. & C. The Surveyors are requested not to write on or below the space for Committee's Minute.

Insert Character precisely as in Register Book.