

# REPORT of SURVEY for REPAIRS, &c.

2953  
WED 9 JULY 1890

No. 9953 Date of Writing Report 18 Port of Glasgow  
 No. in Reg. Book 325 Survey held at Glasgow Date, First Survey 11 June Last Survey 7th July 1890  
 on the Iron B. Kingdom of Sweden Master Copper

TONNAGE:— NET 788 GROSS 830 UNDER DEK. 727  
 Built at Sunderland By whom Ironsides & Foster When 1875  
 Owners J. & S. Smith Port belonging to London

Owner's Address (if not already recorded in Appendix to Register Book.)  
 If Surveyed Afloat or in Dry Dock Dry Name of Dock Jovan Destined Voyage New Zealand  
 Length of Poop ft.: of Forecastle ft.: of Raised Or. Deck ft.: Moulded Depth ft. ins.  
 (if these particulars are not yet recorded in the Register Book.)

Last Survey, No. 49713 Port Row Classed S.S. Bro 103-10.87 100A.1  
 (State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard) in Summer ft. ins.  
 Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials (if assigned) as painted on Ship in Winter ft. ins.  
 of any letters respecting this case.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Annual Survey.  
 The bottom examined scraped & chipped and repainted. The planks of Rudder bushed. A new mizen topmast fitted and the stays, backstays & topmast rigging to mizen renewed of J.S. wire.

State if a Report is also sent on the Machinery of the Ship or if not whether, and when, one will be sent

Insert Character precisely as in Register Book.

PRESENT CONDITION OF THE	Plating	Plating	Plating	Plating
Decks	Good	Plank (Bottom) & Counter	Good	Ceiling
Waterways	✓	Treenails or Rivets	✓	Rudder
Comings	✓	Breasthooks and Stemson	✓	Windlass & Capstan
Up'r Dk. Beams & Fastenings	✓	Transoms, Pointers, & Crutches	✓	Pumps
Low'r Dk. Beams & Fastenings	✓	Timbers of Frame at the opening	✓	Cement (if Iron Ship)
Planksheers	✓	ditto ditto at other places	✓	Caulking of Bot'm, D'k, & Watrways
Sheerstrakes	✓	Keelsons	✓	Copper, or Y.M. (State if on Felt.) When put on
Topsides	✓	Clamps & Shelves	✓	Boats
Wales	✓	Coal Bunker, Openings, Lids, &c.	✓	Masts, Yards, &c.
Engine Room Skylights	✓	Scuppers	✓	Condition, how ascertained
General Observations, Opinion as to Class, Recommendation, &c.:		Cargo & Main Hatchways	✓	Sails
		Hatches	✓	Anchor No. of 3 B.S. 2 1/2
				Cables Parteen
				Hawsers & Warps
				Standing & Running Rigging

This vessel is in good condition in my opinion eligible to remain as classed & to have record of survey to 6.90

Entry Fee (if chargeable) per Scale I., Sec. 27...	Office Fee (if chargeable) per Scale II., Sec. 27...	Survey Fee (per Section 28)	Special on Damage, Fee (if any) (per Sec. 29)	*Certificate (if required) to be sent as per margin	Travelling Expenses (if chargeable)	Second Surveyor's Fee (if any)
£	£	£	£	£	£	£

Committee's Minute ✓ FRI 11 JULY 1890  
 Character assigned 100A.1

Fees applied for, 18  
 Received by me, 18  
 J. D. ...  
 Surveyor to Lloyd's Register of British & Foreign Shipping.

Form No. 2 for Repairs—10000—13 8/83—Transfer Ink—T & S J  
 The Surveyors are requested not to write on or below the space for Committee's Minute.