

REPORT of SURVEY for REPAIRS, &c.

10210

No. 10210 Date of Writing Report 18 Port of Glasgow Received in London Office, MEN 20 OCT 1890
 No. in Survey held at Glasgow Date, First Survey 16 Sept Last Survey 16 October 1890
 Reg. Book Suppl on the Steel S.S. Ethelwold (No. of Visits 2) Master Bernpohl
 YEAR. 90 MONTH.

TONNAGE:—
 NET 533 Built at Belfast By whom Worthman, Clark & Co When 1890
 GROSS 958 Owners Coburn, Rowden & Co Port belonging to Glasgow
 UNDER DK. 572 Owners' Address Glasgow
 (if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock Afloat Name of Dock Queens Destined Voyage Boston
 Length of Poop ft.: of Forecastle ft.: of Raised Or. Deck ft.: Moulded Depth ft. ins.
 (if these particulars are not yet recorded in the Register Book.)

Last Survey, No. 3770 Port Bel Classed Contemplated 100A!
 (State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.)
Receipts 15.9.90 & Belfast 24.9.90 as painted on Ship } in Summer ft. ins.
 Society's Freeboard (if assigned) } in Winter ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Completion after machinery was put in place.

The Engine & Boiler hatchway Comings & Casings & deck flat at sides of same properly secured in place. The following steel & manilla hawsers put on board in completion of the vessel's equipment.

Supplied to vessel		Paid by Parties	
Yds		Equip	Part
60	3/4 steel	60	3/4 steel
90	3 —	90	3
90	9/16 manilla	90	7
120	5 —	90	5
20 90	1/2 —		
20 120	1 —		
10 120	3 —		

Dimensions 208.15 x 28.15 x 12.7
 Tonnage u. D. 571.57
 Inm. Dk. 341.81
 R. Dk. 66.25
 L. Dk. 36.05
 Gross 955.68
 P. P. Space 382.92
 Crewspace 37.58
 Act. Eq. 5.78
 Red Ry 422.28
533.40

PRESENT CONDITION OF THE			
Decks	Blank (Bottom) & Counter	Ceiling	Boats
Waterways	Treenails or Rivets	Rudder	Masts, Yards, &c.
Comings	Breasthooks & Stemson	Windlass & Capstan	Condition, how ascertained
Up'r Dk. Beams & Fastenings	Transoms, Pointers, & Crutches	Pumps	Sails
Low'r Dk. Beams & Fastenings	Timbers of Frame at the openings	Cement (if Iron Ship)	Anchors No. of
Planksheers	Ditto ditto at other places	Caulking of Bot'm, D'k, & Watrways	Cables
Sheerstrakes	Keelsons	Copper, or Y.M. (State if on Felt.) When put on	Hawsers & Warps
Topsides	Clamps & Shelves		Standing & Running Rigging
Wales			
Engine Room Skylights	Coal Bunker, Openings, Lids, &c.	Scuppers	Cargo & Main Hatchways
			Hatches

General Observations, Opinion as to Class, Recommendation, &c. :
The work now done to hull is of a satisfactory character & the parts equipment supplied not less than req'd by tables

Entry Fee (if chargeable) per Scale I., Sec. 27...	£	:	:	Fees applied for, 18 Received by me, 18 <u>A. Danvers</u> Surveyor to Lloyd's Register of British & Foreign Shipping.
Office Fee (if chargeable) per Scale II., Sec. 27...	£	:	:	
Survey Fee (per Section 23)	£	:	:	
Special on Damage, Fee (if any) (per Sec. 25)	£	:	:	
*Certificate (if required) to be sent as per margin	£	:	:	
Travelling Expenses (if chargeable)	£	:	:	
Second Surveyor's Fee (if any)	£	:	:	

Committee's Minute
 Character assigned See First Entry Report

FRI 24 OCT 1890



State if a Report is also sent on the Machinery or if not whether, and when, one will be sent.

Insert Character as in Register Book.