

REPORT of SURVEY for REPAIRS, &c.

No. 10685

Date of Writing Report 18 May 1891

Port of Glasgow

Received in London Office,

No. in Reg. Book.

Survey held at Bowling

Date, First Survey 15 May 1891 Last Survey 15 May 1891

278 on the Iron Steamer "Emerald"

(No. of Visits)

Master J. McEwan

YEAR.

MONTH.

TONNAGE:-

NET 152

Built at Paisley

By whom J. Fullerton & Co

When 1889.

GROSS 404

Owners W. Robertson

Port belonging to Glasgow

UNDER DK. 310

Owners' Address

(if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock Slipway Name of Dock Bowling

Destined Voyage

Length of Poop ft.: of Forecastle ft.: of Raised Or. Deck ft.: Moulded Depth ft. ins.

Years assigned, if a Wood Ship.

Character in Register Book.

Last Survey, No. 9822 Port GLS

Classed

+ Lmb. 7.89

100A 1

5.90

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.)

Society's Freeboard (if assigned) as painted on Ship

in Summer

ft. 10 ins.

in Winter

ft. 11 ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Annual Survey

above helms statutory dk line.

Vessel placed in dry dock. Bottom cleaned and painted. About a dozen started and wasted rivets reamed on each side at the fore end of flat of bottom.

PRESENT CONDITION OF THE

Decks	Sound	Plank (Bottom) & Counter	Sound	Ceiling	Sound	Boats	Sound
Waterways	"	Treenails or Rivets	"	Rudder	"	Masts, Yards, &c.	"
Comings	"	Breasthooks & Stemson	"	Windlass & Capstan	"	Condition, how ascertained	From dk
Up'r Dk. Beams & Fastenings	"	Transoms, Pointers, & Crutches	"	Pumps	"	Sails	Sound
Low'r Dk. Beams & Fastenings	"	Timbers of Frame at the openings	"	Cement (if Iron Ship)	"	Anchors No. of	38 + 8. 1K
Planksheers	"	Ditto ditto at other places	"	Caulking of Bot'm, D'k, & Watrways	"	Cables	part seen Sound
Sheerstrakes	"	Keelsons	"	Copper, or Y.M. (State if on Felt.)	"	Hawsers & Warps	"
Topsides	"	Clamps & Shelves	"	When put on	"	Standing & Running Rigging	"
Wales	"					Hatches	"
Engine Room Skylights	"	Coal Bunker, Openings, Lids, &c.	"	Scuppers	Sound	Cargo & Main Hatchways	Sound

General Observations, Opinion as to Class, Recommendation, &c.:

She is now in a good and efficient condition and eligible in my opinion to remain as classed with record of survey 6ly. 5. 91.

Entry Fee (if chargeable) per Scale I., Sec. 27...	£	✓	:	:	Fees applied for,
Office Fee (if chargeable) per Scale II., Sec. 27...	£	✓	:	:	
Survey Fee (per Section 28)	£	✓	:	:	
Special on Damage, Fee (if any) (per Sec. 28)	£	✓	:	:	
*Certificate (if required) to be sent as per margin	£	✓	:	:	
Travelling Expenses (if chargeable)	£	✓	:	:	Received by me,
Second Surveyor's Fee (if any)	£	✓	:	:	18

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute Fri. 22 MAY 1891

Character assigned 100A 1