

REPORT of SURVEY for REPAIRS, &c.

No. 10965

Date of Writing Report

18th September 91 Port of Glasgow

Received in London Office,

NOV. 21 SEP 1891

No. in Reg. Book.

Survey held at

Glasgow

Date, First Survey

Sept 15th

Last Survey

17th Sept. 1891

539 on the

Iron Ship "Egnes Oswald"

Master D. Nicol

YEAR.

MONTH.

TONNAGE:—
NET 1380

Built at Port Glasgow

By whom H. Murray & Co

When 1876

5th

GROSS 1447

Owners J. Law & Co

Port belonging to Glasgow

UNDER DK. 1314

Owner's Address

(if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock

Dry dock

Name of Dock

Govan

Destined Voyage

Santiago.

Length of Poop

ft.: of Forecastle

ft.: of Raised Or. Deck

ft.: Moulded Depth

ft.

ins.

(if these particulars are not yet recorded in the Register Book.)

Last Survey, No.

36333

Port

Live

Classed

S. S. Hull 7123-11.88

100A1

11.90

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard (if assigned) as painted on Ship

in Summer

4 ft.

7 ins.

in Winter

ft.

ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Annual Survey.

Vessel placed in dry dock - bottom cleaned, examined, and repainted. Rudder pintles rebushed + rudder plating patched on port side.

PRESENT CONDITION OF THE

Decks	Good	Plating	Good	Ceiling	Good	Boats	Good
Waterways	"	Plank (Bottom) & Counter	"	Rudder	"	Masts, Yards, &c.	"
Comings	"	Transoms or Rivets	"	Windlass & Capstan	"	Condition, how ascertained	From deck
Up'r Dk. Beams & Fastenings	"	Breasthooks and Stemson	"	Pumps	"	Sails	Good
Low'r Dk. Beams & Fastenings	"	Transoms, Pointers, & Crutches	"	Cement (If Iron Ship)	"	Anchors	No. of 3B. 1S. 2K.
Planksheers	"	Transoms of Frame at the openings	"	Caulking of Bot'm, D'k, & Wat'rways	"	Cables	part seen - good
Sheerstrakes	"	Ditto ditto at other places	"	Copper, or Y.M.	✓	Hawsers & Warps	"
Topsides	"	Keelsons	"	(State if on Felt.)	✓	Standing & Running Rigging	"
Wales	"	Clamps & Shelves	✓	When put on	✓	Hatches	"
Engine Room Skylights	✓	Coal Bunker, Openings, Lids, &c.	"	Scuppers	Good	Cargo & Main Hatchways	Good

General Observations, Opinion as to Class, Recommendation, &c.: This vessel is in a good and sufficient condition, eligible, in our opinion, to remain as classed with fresh record of survey Gl. 9. 91.

Entry Fee (if chargeable) per Scale I., Sec. 27...	£	:	:
Office Fee (if chargeable) per Scale II., Sec. 27...	£	:	:
Survey Fee (per Section 28)	£	:	:
Special on Damage, Fee (if any) (per Sec. 28)....	£	:	:
*Certificate (if required) to be sent as per margin	£	:	:
Travelling Expenses (if chargeable)	£	:	:
Second Surveyor's Fee (if any)	£	:	:

Fees applied for,

18

Received by me,

18

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

TUES. 22 SEP 1891

Character assigned

100A1