

# REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 26<sup>th</sup> Oct. 1892 When handed in at Local Office 26<sup>th</sup> Oct. 1892. Port of Glasgow 28 OCT 92

Survey held at Glasgow Date, First Survey 18<sup>th</sup> Oct. Last Survey 21<sup>st</sup> Oct. 1892

on the Iron S.S. "B. Kemény" Master R. Lagger

Built at Dumbarton By whom Burrell & Son When 1881 MONTH 12

Owners Royal Hungarian Sea Nav. Co. (Ltd.) Port belonging to Fiume

Owners' Address (if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? Afloat Name of Dock Queen's

Destined Voyage Fiume

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. 100 A 1 8.92 S.S. Val. N° 3-11-91

CHARACTER. 100 A 1 8.92 S.S. Val. N° 3-11-91

Society's Freeboard (if assigned) as painted on Ship and now verified

REPAIRS, OR EXAMINATION AS PER RULE, FOR Completion of Equipment.

A bower anchor being lost, a new one was now supplied and the following are the particulars obtained from the anchor, but as no opportunity was afforded of comparing the certificate with the anchor, it is recommended that this be done at the first opportunity.

New Anchor { Cert. N° 32916. weight of anchor 23-3-6 Equip. N° 0

Anchor { .. Stock 5-3-14 Test 23-15-2-14

Anchor { Cert. N° 12064. weight of anchor 23-1-25

lost. { .. Stock. 4-3-15 Rule wts 23 1/2 cwt

The vessel being loaded a general examination could not be made.

SUMMARY OF DAMAGE REPAIRS: Plates, Paired or Repaired: Frames, ditto. Plates, Renewed: Frames, ditto. Other Repairs.

PRESENT CONDITION OF THE		Good	
Decks	Transoms, Pointers, & Crutches	✓	Good
Waterways	Timbers of Frame at the openings	✓	"
Coamings	Ditto ditto at other places	✓	"
Up'r Dk. Beams & Fastenings	Keelsons	✓	"
Low'r Dk. Beams & Fastenings	Clamps, Shells & Stringers	✓	"
Plating	Ceiling	✓	"
Planking	Cement or Asphalt	✓	"
Treenails or Rivets	Tanks	✓	"
Breasthooks & Stemson	Caulking of Bot'm, D'k, & Wat'rw'ys	✓	"
	Copper, or Y.M.	✓	"
	(State if on Felt.)	✓	"
	When put on, Month	✓	"
	Rudder	✓	"
	Windlass & Capstan	✓	"
	Pumps	✓	"
	Engine Room Skylights	✓	"
	Coal Bunker, Open'gs, Lids, &c.	✓	"
	Scuppers	✓	"
	Cargo & Main H'tch'w'ys	✓	"
	Hatches	✓	"
	Boats	✓	"
	Masts, Yards, &c.	✓	"
	Condition, how ascertained	✓	"
	Sails	✓	"
	Anchors No. of	✓	"
	Cables, length	✓	"
	(State if now ranged)	✓	"
	Hawsers & Warps	✓	"
	Standing & Running Rigging	✓	"

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:- "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9,91," or "to remain as classed and to have record of survey, 9,91, and the notations of ss No. 1-91 and ptND91, &c."

This vessel appears to be in a good condition and eligible, in my opinion, to remain as classed, without fresh record of survey.

Office Fee (if chargeable) per Scale II, Sec. 27

Survey Fee per Section 28

Special Damage or Repair Fee (if any)

Travelling Expenses (if chargeable)

Second Surveyor's Fee (if any)

\*Is Certificate now required?

Committee's Minute


Character assigned

Deferred for survey of expt.

White Own 22/11/92 Rpt to Nat 20/12/92

R. Elliott

Surveyor to Lloyd's Register of British & Foreign Shipping.



© 2019

Lloyd's Register Foundation

GLS166-0174