

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 15. When handed in at Local Office 15. Port of Glasgow MON. 20 MAR 1893
No. in Reg. Book 656 Survey held at Glasgow Date, First Survey 14th March Last Survey 15th March 1893
Master H. Munnell

TONNAGE:-
GROSS 1457 Built at Sunderland By whom J Blumer & Co When 1888 10
UNDER DK. 1058 Owners Robinson Bros Port belonging to Whitty
NET 945 Owners' Address
Surveyed Afloat or in Dry Dock? Afloat Name of Dock ✓ Destined Voyage
WB= DBa tons; f tons; uE&B tons; Cell DB tons; }
FPT tons; APT tons; MT tons. }
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements.)

Last Survey, No. 10980 Port Gf

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE, FOR Damage sustained through collision with the S. S. "Rosalind" of Chester.

On starboard side abovest fore hatchway, four feet of gunwale angle set fair in place and recaulked, the upper part of a bolt of a sheerstrake plate re-riveted, two bulwark stanchions faired and replaced.

SUMMARY OF DAMAGE REPAIRS: ✓ Plates, Faired or Repaired; ✓ Frames, ditto. ✓ Plates, Renewed; ✓ Frames, ditto. Other Repairs: ✓ two bulwark stanchions gunwale angle, sheerstrake bolt

PRESENT CONDITION OF THE			
Decks	Good	Transoms, Pointers, & Crutches	Good
Waterways		Timbers of Frame at the openings	
Coamings		Ditto ditto at other places	
Up'r Dk. Beams & Fastenings		Keelsons	not out
Low'r Dk. Beams & Fastenings		Clamps, Shelves & Stringers	
Plating		Salting	✓
Planking		Ceiling	Good
Stanchions or Rivets		Cement or Asphalt	not exam'd
Breasthooks & Stemson		Tanks	not tested
		Caulking of Bot'm, D'k, & Wat'rw'ys	Good
		Copper, or Y.M.	✓
		(State if on Felt.)	
		When put on, Month	Year
		Rudder	part seen good
		Windlass & Capstan	Good
		Pumps	
		Engine Room Skylights	
		Coal Bunker, Open'gs, Lids, &c.	
		Scuppers	
		Cargo & Main H'tch'w'ys	
		Hatches	Good
		Boats	
		Masts, Yards, &c.	
		Condition, how ascertained	from deck
		Sails	Good
		Anchors No. of	38-15-2K
		Cables, length	put seen size
		(State if now ranged)	to
		Hawsers & Warps	Good
		Standing & Running Rigging	

General Observations, Opinion as to Class, Recommendation, &c.:-
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9,91," or "to remain as classed and to have record of survey, 9,91, and the notations of ss No. 1-91 and ptND91, &c."


This vessel appears in a good and efficient condition and in my opinion eligible to remain as classed and to have record of survey 3.93

Office Fee (if chargeable) per Scale II., Sec. 37 £ : : Fees applied for, £ : :
Survey Fee (per Section 28) £ : : 18
Special Damage or Repair Fee (if any) (per Sec. 28.) £ 1 : 1 : Received by me, £ : :
Travelling Expenses (if chargeable) £ : : 18/9
Second Surveyor's Fee (if any) £ : :
*Is Certificate now required? £ : :
Committee's Minute
Character assigned

TUES. 21 MAR 1893

100A1

Surveyor to Lloyd's Register of British & Foreign Shipping.



GLS167A-0116

To a Report also sent now on the Machinery of the Ship? If not, state whether, and when, one will be sent?

Form No. 2 for Repairs—206.—L.R.F.F.—20,000.—24.—
(The Surveyors are requested not to write on or below the space for Committee's Minute.)
* Certificate to be sent to

N.B.—All alterations in the existing records should be underlined.