

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 18 When handed in at Local Office 18

Port of Glasgow

No. in Reg. Book.

Survey held at Glasgow

Date, First Survey

Last Survey 28 Dec 1894

3 in Sup on the Wood, Iron or Steel Steamer "Ailsa"

(No. of Visits

Master H. B. Burt

YEAR.

MONTH.

TONNAGE:-

Built at Troon

By whom Ailsa S. B. Co.

When 1894

GROSS 325

Owners F. B. Hiven

Port belonging to Troon

UNDER DK. 220

NET 74

Owners' Address

Surveyed Afloat or in Dry Dock? Afloat

Name of Dock headrowide

Destined Voyage coasting

WB= DBa tons; f tons; uE&B tons; CellDB tons; FPT tons; APT tons; MT tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.	Year Assigned	Machinery and Boiler Surveys
* for Special Survey, Date of last Survey and of Periodical Surveys.	now expired.	(including date of N.B., if any).
100A.1		
New hull		
12.94		

Last Survey, No. 13370 Port GL

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.

Society's Freeboard (if assigned) as painted on Ship and now verified

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Striking buoys during heavy weather. on

the 22nd Decr 1894

hull has been placed in shipway the bottom examined and found to be in good condition

SUMMARY OF DAMAGE REPAIRS:— Plates, Fair'd or Repaired; Frames, ditto. Plates, Renewed; Frames, ditto. Other Repairs.

PRESENT CONDITION OF THE

Decks	Transoms, Pointers, & Crutches	Copper, or Y.M. (State if on Felt.)	Hatches
Waterways	Timbers of Frame at the openings	When put on, Month Year	Boats
Coamings	Ditto ditto at other places	Rudder	Masts, Yards, &c.
Up'r Dk. Beams & Fastenings	Keelsons	Winglass & Capstan	Condition, how ascertained
Low'r Dk. Beams & Fastenings	Clamps, Shells & Stringers	Pumps	Sails
Plating	Salting (State if examined.)	Engine Room Skylights	Equipment letter
Planking	Ceiling	Coal Bunker, Open'gs, Lids, &c.	Anchors, No. of
Treenails or Rivets	Cement or Asphalt (State which.)	Scuppers	Cables (State if now ranged)
Breasthooks & Stemson	Tanks (State if now tested.)	Cargo & Main H'tchw's	length size
	Caulking of Bot'm, D'k, & Wat'rw'ys		Rule length size
			Hawsers & Warps
			Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9,91," or "to remain as classed and to have record of survey, 9,91, and the notations of ss No. 1-91 and ptND91, &c."

This vessel is in my opinion eligible to remain as classed and to have record of survey 12.94

Office Fee (if chargeable) per Section II., Sec. 27	2	Fees applied for,
Survey Fee (per Section 28)	2	18
Special Damage or Repair Fee (if any) (per Sec. 28.)	2	Received by me,
Travelling Expenses (if chargeable)	2	18
Second Surveyor's Fee (if any)	2	
*Is Certificate now required?		

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

Character assigned

TUES. 8 JAN 1895

100A.1



© 2019

Lloyd's Register Foundation

GLS171-0140