

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report... 18... When handed in at Local Office... 18... Port of Glasgow

No. in Reg. Book... Survey held at Glasgow Date, First Survey 20 June Last Survey 10 July 1899.

1207 on the Wood, Iron or Steel S. S. Shakhallan Master

TONNAGE:— Built at Glasgow By whom Russell & Co. When 1890 7

GROSS 2336 Owners Russell & Co. (see below) Port belonging to Glasgow

UNDER DEK. 1724 Owners' Address (if not already recorded in Appendix to Register Book.)

NET 1489 Surveyed Afloat or in Dry Dock? Both Name of Dock Govan & Co. Destined Voyage Cardiff

WB=CellDBo... 242 feet; uE&B... feet; J... feet; } Particulars of Classification (which must be inserted precisely as in Register Book & Supplements.)

total capacity 500 tons. FPT... tons; APT 54 tons; MT... feet tons. }
N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 3131 Port Glasgow

REPAIRS, OR EXAMINATION AS PER RULE, FOR Completion of S. S. No. 2

Vessel placed in dry dock, bottom cleaned & examined. Cables ranged & examined. Peaks cleared & examined. After peak tank examined and tested. Bunkers cleared & examined, close ceiling being removed from same as required by the rules. Masts, spars, rigging, pumps, sluices, w.f. doors, steam operating engine & connections, and general equipment examined. Holds and bunkers above close ceiling sealed & recoated. This vessel is about to proceed to Cardiff where she will probably be transferred to new owners (Stamati Vafiadachi, of Ladopoulos & Ladopoulos firm and Ioannis Poyllas) & probably have her name changed.

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

PRESENT CONDITION OF THE	Stringers	Engine Room Skylights	Boats
Decks <u>Good</u>	<u>Good</u>	<u>Good</u>	<u>Good</u>
Caulking of Decks	after peaks <u>Good</u>		
Waterways			
Coamings			
Beams & Fastenings			
Outside Plating			
Caulking of ditto			
Rivets			
Breasthooks & Crutches			
Transoms			
Frames			
Reverse Frames			
Floors			
Keelsons			
	Inner Bottom Plating	Coal Bunkers, Open'gs, Lids, &c.	Masts, Yards, &c.
	State if Tanks now tested	Scuppers	Condition, how ascertained
	Bulkheads	Cargo Hatchways	(State if wedges removed)
	Ceiling	Hatches	Sails
	Cement on top of (State which.)	Planking of Wood Vessels	Equipment letter
	Rudder	Treenails ditto	Anchors, No. of
	Windlass	Breasthooks & Stemson ditto	Cables (State if now ranged)
	Have Pumps now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	" length (on board)
	Have Sluice Valves now been examined and found efficient?	Timbers of Frame at openings ditto	" Rule length (per Table 22)
	Have Watertight Doors now been examined and found efficient?	Ditto ditto at other places ditto	Hawsers & Warps
	Dblng. Plates under Sounding Pipes	Salting (State if examined.) ditto	Standing & Running Rigging
		Copper, or Y.M. (State if on Fest.) ditto	
		When put on, Month Year	

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptND98, &c."

This vessel is eligible, in my opinion, to remain as classed and to have record of survey 7, 99 and the notation of S. S. No. 2-99.

Office Fee (if chargeable) per Scale II, Sec. 27... £... Survey Fee (per Section 25)... £... Special Damage or Repair Fee (if any) (per Sec. 28.)... £... Travelling Expenses (if chargeable)... £... Second Surveyor's Fee (if any)... £...

Fees applied for, 19/7 1899 Received by me, [Signature] Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute Character assigned

1000A pt. Arch. dk. w. fbd. + LMC 3,99

Has a Survey also been held on the Machinery of the Ship? If so, is the Report sent now, or when will it be sent?

Is Certificate required? If so to be sent to

