

No. 3494.

(Received at London Office,

**TESTS OF BOILER STEEL.**

Tests of 1 Steel Plate manufactured by Messrs D. Colville & Sons of Motherwell  
 for Boiler No. 198/9 to be constructed by Messrs Hutson & Corbett of Glasgow  
 for Messrs A. M. Mullan & Sons S. I. Nos 271-3. 240 & 2

Date first visit March 25<sup>th</sup> 1886 last visit \_\_\_\_\_ No. of visits \_\_\_\_\_

The \_\_\_\_\_ specified in the accompanying copy of Advice Notes were rolled from  
 charges. The tensile test has been applied to 1 samples as set forth below,  
 and the temper and bending tests to a shearing from the plate

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge.	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins.	Remarks.
					Thickn.	Brlth.	Area.	Total.	Sq. Inch		
					Ins.	Ins.	Ins.	Tons.	Tons.	%	
1	Shell Plate C476			7336	1.35	1.365	1.529	42.67	27.5	26.0	
											MD 12-4-86

Fee ..... £ : :  
 Expenses £ : :  
 £ : :

To be paid by \_\_\_\_\_



© 2021

A. N. Dove  
 Surveyor, Lloyd's Register  
 Glasgow  
 6.4.86