

No. 6818

**TESTS OF BOILER STEEL.**

Tests of 3 Steel Plates manufactured by Messrs DeLorville & Sons of Motherwell for Boiler No. 344/5 to be constructed by Messrs W. King & Co of Glasgow for Messrs Workman Clark & Co's S. S. No. 55 & 56.

Date first visit March 5<sup>th</sup> 1888 last visit March 9<sup>th</sup> 1888 No. of visits

The \_\_\_\_\_ specified in the accompanying copy of Advice Notes were rolled from \_\_\_\_\_ charges. The tensile test has been applied to 1 sample as set forth below, and the temper and bending tests to a shearing from each plate with satisfactory results.

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge.	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins. %	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch.		
					Ins.	Ins.	Ins.	Tons.	Tons.		
1	Butt Strap for side	G516		724	1.03	.91	.937	27.20	29.0	27.5	

W.P. 14/3/88

Fee ..... £ : :  
 Expenses £ : :  
 £ : : To be paid by

© 2021  
 H.M. Dove  
 Surveyor, Lloyd's Register  
 Glasgow  
 9.3.88