

Sent to Chief Surveyor

Received from Chief Surveyor

VESSEL'S NAME

27.96
Lds Colina

Report

Glo

No.

13971

For the CHIEF SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

2nd. No. 3

SURVEY PARTLY HELD.

When due

5, 95

When proposed to be completed

Vessel lying up.

Portion of Survey held, &c.

The Second S.S.No.3 became due in May, 1895.

In September last the vessel changed ownership, and the bottom was examined in dry dock as part of the survey. The Boiler Survey was held. The Owners desired to postpone the completion of the survey on the hull for about two months, during which time it was intended to make two voyages to Iceland, and then to lay the vessel up for survey.

This was approved by the Committee on the 8th. October last.

In reply to enquiry the Glasgow Surveyors now state that they are informed the vessel is still lying in the Gareloch.

It is submitted the Owner should be reminded of his undertaking with the Glasgow Surveyors in September last "to complete the survey in about two months time; and in view of the fact that the year of grace expired at the end of May last, he should be requested to state what action he purposes taking in the matter, and he should be requested to furnish the usual guarantee in the event of the vessel being offered for sale. In the meantime the class might be allowed to remain undisturbed.

H.S.
3.7.96.



© 2021

Lloyd's Register
Foundation