F.E.

Received by Chief Surveyor 6.2.00 — now Amubis — Received from Chief Surveyor

VESSEL'S NAME Stl SS "Val de Travers" Report Gfs No. 17666

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	3/20 on	Proportions
Spar Sheerstrake . .	✓	✓
Description of Framing:—	Ordinary	

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ✠ 100 A1 (Steel) as recommended

✠ 100 A1 Steel "Well Dk"
1 Dk (Iron) "Well Deck"
NB = Cell DB of 115' 183t FPT 70t. APT 8t.
F.K. 3 BH CEM "A & CP" Mchy Aft.
Q 103' B 13' F 27'.

BJS 6/2/00

C.H.S.

© 2019 Lloyd's Register Foundation
GLS285-0077

" " in Hold " " — — — — — —
B FRAMES, In Fore Body, No. and Spacing — — — — — —

" ~~Tie Plates~~ ..... Plate under windlass
Deck Material and thickness Iron