

Report to Chief Surveyors 11. 12. 00 Received from Chief Surveyors

VESSEL'S NAME Steel S. S. "Dunbar" Report Gls. No. 18514.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/6/92.)

Nature of Survey When due

± 100 A1 (Steel)
2 Dks (SH) & web frames.
WB = Cell DB a 114' u 8y B 38' f 152 801t APT62t
FK. 6 BH. Cem. A & CP.
P 34' B 106' F 36'

S. H. T.
11/12/00



Table with 4 columns: WEB-FRAMES, In Fore Body, No. and spacing, 10, 6 spaces, 10, 6 spaces. Includes rows for Angle on ditto and Tie Plates.

Vertical text on the right edge of the page, including 'ry D', 'ks wit', 'rs of', 'ound', 'm, Up', 'hes in S', 'x2', 'x6', '1x', '9', '6', 'Inches in Ship', '0', '4', '3', '3', '55', 'x', '55', '4', '27', 'x3', '12', '3', '40', 'x3', '12', '3', '7', '35', '12'.