

# PARTICULARS for RECORD OF DOUBLE BOTTOMS, &c., in LLOYD'S REGISTER.

No. of Report Off. 8784  
No. in Register Book \_\_\_\_\_

Port

Greenock

(Received at London Office, \_\_\_\_\_ r88.)

Date

19<sup>th</sup> Nov/84

On the

Saw Steer "Coila"

Double bottom, aft, length \_\_\_\_\_ and water capacity in tons \_\_\_\_\_ . Double bottom, forward, length \_\_\_\_\_ and water capacity in tons \_\_\_\_\_

Double bottom, under engines and boilers, length \_\_\_\_\_ and water capacity in tons \_\_\_\_\_ . If under Engines only, or Boilers only, state which \_\_\_\_\_

Double bottom, constructed on the cellular system, length \_\_\_\_\_ and water capacity in tons \_\_\_\_\_

Fore peak tank, water capacity in tons 25 . After peak tank, water capacity in tons 15 .

Midship deep tank, length \_\_\_\_\_ and water capacity in tons \_\_\_\_\_ . Other tanks, if fitted, length \_\_\_\_\_ and water capacity in tons \_\_\_\_\_

The above have ..... been tested as required by the Rules,  
(If necessary, furnish further information by sketch.)

Surveyor to Lloyd's Register of British and Foreign Shipping.