"Maria Rickmers"
Greenock Report No 11457.

23.3.91.

No 267
Scale ¼ inch = 1 foot

Lower deck

Engine & Boiler Space

Fresh water tank

Stiffening at after tank

Section at frame No 21

Section at frame No 28

Section at frame No 34

Lower deck

Centre Bulkhead

Water ballast tank

Line of lower deck

Stiffening at deep tank

Line of tank edge

Line of lower deck

Keelson

Stiffening at fife Keelson in way of deep tank 1" Scale

Line of tank edge

Line of lower deck

Keelson

GRH319-0194

"Maria Rickmers."

Guenock Report

No. 10457.

Rickmers Reis Rhd.

Reis & Co

Duisburg a/Rhein.

© 2019 Lloyd's Register Foundation

GR4319-01 47