

Less Crew Space.  
Less above Crown of

41.26

Length on deck from after part of stem to fore part of  
stern post

225.11

Managers

1.

Sent to Chief Surveyors

3.7.00

Received from Chief Surveyors

VESSEL'S NAME

Steel S.S. "Kotuku"

Report

Grk

No.

12731

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

1st entry

When due

± 100 A1 ("Steel").

10k (Stl) & deep framing. Well deck.

WB = Cell DBa 52' u & 19' f 96' 274t. FPT 43t APT 32t.

7K. 4BH. Cem. A&CP.

Q 77'. B 56' F 28'.

J.H.T.

3/7/00

C.H.P.



© 2019

Lloyd's Register  
Foundation

GRK352-0002

in Hold

Tie Plates

Deck Material and thickness