

Port of Port Glasgow

23<sup>rd</sup> May 1904

REPORT ON MASTS, SPARS, AND RIGGING.

Mr. Collist

Having, in accordance with your instructions, examined the Masts, Spars, and Rigging, and Iron Work of same, of the S. S. Briardene of Newcastle have to report that I found the above in a satisfactory condition, after undergoing repair

J. W. Whitehead  
Dock & Ship Master

L. 10/-

The Surveyors,  
Lloyd's Register of British & Foreign Shipping,



© 2020

Lloyd's Register  
Foundation

GRC354-0179

safe working condition and eligible, in our opinion