

Chief Surveyor 25.11.95

Received from Chief Surveyor

NAME Steel S.S. "Ras Elba"

Report Hpl. No. 9827

Records of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

## CLASSIFICATION.

|      | Additions (if any)<br>required by Rules.         | On account of |
|------|--|---------------|
| Stk. | add $\frac{1}{20}$ & Awng Dk. side<br>increased. | Proportions   |
| Stk. | ✓  |               |

This vessel appears to have been built in accordance with the Rules and the approved plans. It is submitted she is eligible for classification "100A1 (Steel) Part awning deck, with freeboard" as recorded: the Summer freeboard of 9 ft. from centre of disc to top of upper deck line at part awning deck now marked on the vessel's sides and to be inserted in the classification certificate together with the remaining freeboards shown on the surveying verification form.

100A1 (Steel) "Pt. Awng Dk. with freeboard"  
(pt. Im. pt. Stl) 2 1/2 B. & Web frames & pt. Awng Dk (pt. Im. pt. Stl).  
3 = Cell DB a 96', u E4B 46', f 110', 450t: APT 30t.  
Fk. Cew.

C. R. J.

25.11.95



© 2019

Lloyd's Register  
HPL376-0133