

Received at WEST HARTLEPOOL Office. 6. 11. 1899

Lloyd's Register of British and Foreign Shipping.

(Report on Vessel No. _____)

Port WEST HARTLEPOOLNo pool

And _____

'Verona'No. 4006.ASHIP FORGINGS ~~OR~~ CASTINGS.I have to report that the undermentioned Iron ~~or~~ Steel Forgings ~~or~~ Castings,manufactured by The Darlington Forge Co.of Darlingtonfor the Vessel No. 245, being builtby Messrs Furness Withy & Co.of Hartlepool

have been inspected by me as set forth below, and found to be, so far as can be seen,

sound. Satisfactory as required by the Rules and found
satisfactory

Mark on Forgings.

Lloyd's

No. 4006.ANo. 6Wm H. CameronSunderland 15/11/99

	STERN FRAME.	RUDDER FRAME.	STEM.
Material* ...	<u>Siemens steel</u>	<u>Siemens steel</u>	<u>Siemens steel & scrap iron</u>
How made ...	<u>cast</u>	<u>cast</u>	<u>forged and cast</u>
Dimensions ...	<u>as per plan attached</u>	<u>as per plan attached</u>	<u>as per plans attached</u>
Progress on Inspection	<u>cast tested</u>	<u>cast and tested</u>	<u>forged cast & tested</u>
Date when Inspected	<u>April 21 May 1/99</u>	<u>Aug 9. 25 Sept 14/99</u>	<u>April 21-27 May 1/99</u>

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS, OR PARTICULARS OF TESTS APPLIED TO CASTINGS.

Fee (if any chargeable) £ : :

To be paid at _____



© 2019

Lloyd's Register
Foundation