

2nd. On the plating during the process of riveting
3rd. When the beams were in and fastened,
and before the decks were laid....

construction between 14th Oct 1882 and

REPORT, No. *535 FROM
ON THE Bell Rock

DATE 8/8/83

REMARKS OF THE CHIEF SURVEYOR.

This vessel has now been completed as recommended
by the Hull Surveyors, and having been built in
accordance with the rules and approved drawings
merits the favorable consideration of the Committee
to be classed -1-100 A1 Spar Deck
1 8" (iron) and Spar Deck (iron)
3 Trs Bms

The hull is built in accordance with the Rules.

Lloyd's Register
Foundation